

# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	,												
	ections to OPI from School District:												
	s bus has been sold, retired, or is no longe												
		black ou	t the err	or, C	)PI may ne	need to read it to make the correction.							
OPI County # and County Name			Distri	ct Name									
	07 Cascade						Grea	at Falls I	Public S	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	'ear	Licen			Rated C		****		
	4FD 152702D114 46000			40	04		0.454						
Chan	1FDJE37G3BHA46898 sis Make			19	81	<u> </u>	8451	Rue Type	e: (see ? fo	or defini	16		
Chas	sis iviakė				Body Mak	te		• •	`		,		
	Ford						omas	<b>✓</b> A	□В	_ C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift	Equipped?	1							
☐ Ye	es 🗹 No	I□F	orward	d Fa	acina	Aisl	e Facing 🗹 N	ot Applic	able				
	of Fuel:	Is Bu					ontractor Owned If co			tractor's	name	is <sup>.</sup>	
		1000		Diot	not Owned	• •	ontractor owned in co	illiaotoi ov	viica, com	ilaotoi o	riairio		
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION							
		TC	BE FIL	LEC			GHWAY PATROL						
	This	inspecti	on is for	:	<b>✓</b> 1s	t semes	ster 2nd semes	ster					
_		1	Appro									roved	1_
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in t for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attache		ши			1	
C18	Head lamps					C18	Interior lamps	<u>cu</u>				<del>                                     </del>	
C10	Color					C18	Ceiling - interior					1	
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	or				ļ	
C3	Battery	<u> </u>				C12	Emergency door					<u> </u>	
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re						
C6	Head lamp indicator					C18	Stop lamps	aı				1	
C6	Horn					C18	Marker lamps - rear					<del>                                     </del>	
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no le	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mii	า.)				
C13	Fire extinguisher (5 lbs)					000	Cleanliness					1	
C13	First aid kit Body fluids kit	<b>_</b>				C22 C5	Stop arm No trailer hitch			1		<del> </del>	1
C13	Defroster					Co	Required by forest r	ogulation:				<del> </del>	
C6	Heaters						Shovel (securely faste					1	
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
*Page ni	umber reference, Standards for School Buses in I						equired to wear lap/should	der belts - cu			driver.	1	1
**Does r	not apply. ***New buses ordered after 08/15/02.**	***Based	on origina	al ca	pacity listed	on the m	anufacturers certification to	ag found ins	ide the bus.				
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
Not Approved				Not Approved									
Insped	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	a No.	Date				Badge	e No.			Date			
	ture of District Official	- Duit				Date				- Juil			
Signa	ure of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBG6P1B8HV112666 1987 8502 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Ward Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBG7T1D6YJ512420 2000 8503 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **Bluebird** Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ✓ Forward Facing ☐ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.											
	actions to OPI from School Districts sous has been sold, retired, or is no longer		rice. Ple	ase (	delete it fr	om OPI	's records.						
☐ Ple	ase make corrections noted below. Don't	black ou	it the err	or, O	PI may ne	ed to re	ead it to make the corr	ection.					
OPI County # and County Name					Distri	ct Name							
07 Cascade						Gre	at Falls F	Public S	Schls				
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen	se #		Rated C	Capacity	*****		
	1GBG7T1P7FJ113159			19	0.E		B742				11		
Chass	sis Make				Body Mal	<u> </u>	D/4Z	Bus Type	· (see ? fo	or defini	14		
Cilas	ois iviane				Dody Mar	ve.		• •	•		,		
	Chevrolet						ebird	□ A [	□В	✓ C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?	•							
✓ Ye	es 🗌 No	<b>✓</b> F	orward	l Fa	cina [	☐ Aisl	e Facing  \Quad N	ot Applica	able				
Type	of Fuel:	_					ontractor Owned If co			tractor's	name i	s:	
									,				
<b>✓</b> G	as 🗌 Diesel 🗌 Other						Big Sky Bus	Lines					
					_	CTION							
							GHWAY PATROL						
	This	inspect	ion is for		<b>✓</b> 1s	t semes	ster 2nd semes	ster					
D	the sea l'atant's the Oten dende	1.	Appro		0	D	Irana Parades	d Otalada	.1.	1/		roved	To
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front	1	1		+	C34	Belt cutter **** attach					<del>                                     </del>	+
C18	Head lamps					C18	Interior lamps	-					+
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage					<b>└</b>	<u> </u>
C18	Windshield					C24	Windows					<u> </u>	
C24	Windshield wipers					C13	Warning device					<u> </u>	<del> </del>
C20	Exterior mirrors					C13 C12	Buzzer emergency do Emergency door	oor				<del>                                     </del>	+
C4	Battery Generator or alternator					C12	Red amber signals -	rear				<del>                                     </del>	+
C11	Service door	+				C18	Turn signal lamps - re					+	+
C6	Head lamp indicator					C18	Stop lamps	Jui				<del>                                     </del>	+
C6	Horn					C18	Marker lamps - rear						1
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)				<b>└</b>	
C21	Driver seat belt					C5	Fuel tank	0" ( , ,	`			<u> </u>	<del> </del>
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	1.)			<del></del>	+
C13	Fire extinguisher (5 lbs) First aid kit	<del> </del>				C22	Cleanliness Stop arm					┼─	+
C13	Body fluids kit					C5	No trailer hitch					<del>                                     </del>	+
C11	Defroster					-	Required by forest r	egulation:				<del>                                     </del>	+
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**										driver.		
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspecting Patrol Officer:				Inspe	cting Patrol Officer:								
Badge No Date					Inspecting Patrol Officer:  Badge No Date								
	ture of District Official	_				Date							
g.ia													



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBJ6P1B8FV519221 1985 8536 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Ward **GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ed.											
	actions to OPI from School Districts s bus has been sold, retired, or is no longe		vice. Ple	ase (	delete it fr	om OPI	's records.						
_ ☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, O	PI may ne	ed to re	ead it to make the corr	ection.					
OPI County # and County Name					Distri	ct Name						-	
07 Cascade						Gre	at Falls I	Public S	Schis				
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen			Rated C		****		
01	1GBKP32K5K3317105			19			C553	D.v. T.v.	e: (see ? fo	l£::	14		
Cnas	sis Make				Body Mal	ке		, ,	•		tion)		
	Chevrolet					The	omas	$\square$ A	<b>✓</b> B	□ C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?								-
✓ Y	es 🗆 No		orward	1 =~	oina	□ ∧iol	e Facing	ot Applia	oblo				
								ot Applica					
Туре	of Fuel:	Is B	us:	Distr	ict Owned	<b>✓</b> C	ontractor Owned If co	ontractor ov	vned, con	tractor's	name i	S:	
<b>✓</b> G	as   Diesel  Other						Big Sky Bus	Lines					
					_	CTION							
					OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is for		<b>✓</b> 1s	t semes	ster 2nd semes	ster			A n.n.	round	
Page	Items listed in the Standards	Yes	Appro No	NA	Corr	Page	Items listed in	the Standa	rds	Yes	Appi No	roved NA	Corr
No.*	for School Buses in Montana	163	INO	**	Con	No.*	for School Bus			163	140	**	Con
C17	Identification - front	1				C34	Belt cutter **** attach	ed			1	<del>                                     </del>	+
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior					1	1
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage					<b>↓</b>	
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device					<del>                                     </del>	
C20	Exterior mirrors					C13	Buzzer emergency do	oor			-	<del></del>	-
C3 C4	Battery Generator or alternator	1				C12 C18	Emergency door Red amber signals -	rear				$\vdash$	+
C11	Service door					C18	Turn signal lamps - re					+	-
C6	Head lamp indicator					C18	Stop lamps	Jui					+
C6	Horn	1				C18	Marker lamps - rear				1	<del>                                     </del>	+
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank					<b>↓</b>	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mii	า.)			<u> </u>	
C13	Fire extinguisher (5 lbs)					000	Cleanliness					<del>                                     </del>	_
C13	First aid kit Body fluids kit	1				C22 C5	Stop arm No trailer hitch					—	_
C13	Defroster	1				CS	Required by forest r	ogulation:				┼──	+
C6	Heaters	1					Shovel (securely fast	_			1	+	+
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						+
*Page n	umber reference, Standards for School Buses in later apply. ***New buses ordered after 08/15/02.**						equired to wear lap/should	der belts - cu			driver.		
		DaseC	i on ongini	агυαβ	acity iisted				iue iiie DUS.				
On fi	st inspection, this bus is:						einspection, this bus	is:					
닏	Approved Approved												
Not Approved			_	Not Approved									
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No	Date				Badge	e No			Date			
Signa	ture of District Official			_		Date							



#### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBL6P1B0KV112330 1989 8517 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Ward Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ☐ Gas Diesel ✓ Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	

Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C18 C6 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 Defroster C11 Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

	nis complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the lighway Patrol as soon as all defects are corrected.													
Instru	ictions to OPI from School Distric	t:												
Thi	s bus has been sold, retired, or is no long	er in serv	ice. Pl	ease de	elete it fr	om OPI	's records.							
☐ Ple	ase make corrections noted below. Don't	t black ou	ut the ei	rror, OP	I may n	eed to re	ead it to make the corr	ection.						
OPI C	County # and County Name					Distri	ct Name							
	07 Cascade						Gro	at Falls P	Jublic S	chle				
Vehic	le I.D. # (VIN) - Entire Number		М	odel Ye	ar	Licen		at i alis i	Rated C		****			
	` '													
	1GBL6P1B2KV111812			198			8547		, ,,		71			
Chas	sis Make			B	ody Mal	ke		Bus Type	`		tion)			
	Chevrolet					W	/ard	$\Box$ A	□В №	Z C	$\Box$ D			
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift Ec	quipped?	?								
□ Ye	es 🗹 No	I□F	orwai	rd Fac	ina	☐ Aisl	e Facing 🔽 N	ot Applica	able					
	of Fuel:	Is B					ontractor Owned If co			ractor's	name i	is:		
				,					,					
□G	as Diesel 🗹 Other						Big Sky Bus Lines							
					_	CTION								
TO BE FILLED OUT BY THE HIGHWAY PATROL  This inspection is for:   1st semester  2nd semester														
	Ini	s inspect			<b>✓</b> 18	st semes	ster 2nd seme	ster			۸nn	roved		
Page	Items listed in the Standards	Yes	Nο	roved NA	Corr	Page	Items listed in	the Standar	ds	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**	00	No.*	for School Bus			. 00		**		
C17	Identification - front					C34	Belt cutter **** attach	ied						
C18	Head lamps					C18	Interior lamps					<u> </u>		
C10	Color	_				C18	Ceiling - interior					₩		
C18	Turn signal lamps - front					C21	Seating Floor					<del> </del>		
C18	Turn signal lamps - side (post 1987) Red amber signals - front					C14	Aisle					+		
C18	Marker lamps - front	+				C22	Tools - storage					+		
C18	Windshield					C24	Windows							
C24	Windshield wipers					C13	Warning device							
C20	Exterior mirrors					C13	Buzzer emergency de	oor						
C3	Battery					C12	Emergency door							
C4	Generator or alternator					C18	Red amber signals -					<u> </u>		
C11	Service door	-				C18	Turn signal lamps - re	ear				┼		
C6 C6	Head lamp indicator Horn	+				C18	Stop lamps Marker lamps - rear					┼		
C20	Interior mirror	+				C19	Strobe light - rear ***					+		
C6	Speedometer	1		1		C17	Identification - rear					1		
C2	Brakes					C4	Exhaust system (no l	eaks)				1		
C21	Driver seat belt					C5	Fuel tank							
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min	.)			<u> </u>		
C13	Fire extinguisher (5 lbs)	_				000	Cleanliness					<del>                                     </del>		
C13	First aid kit Body fluids kit	_				C22 C5	Stop arm No trailer hitch					+		
C11	Defroster Defroster					C3	Required by forest i	regulation:				+		
C6	Heaters						Shovel (securely fast					+		
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,						
*Page n **Does r	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.	Montana *****Based	(2002 Ed d on origi	dition). ** nal capa	**Bus dri city listed	vers are i	required to wear lap/shoul anufacturers certification	der belts - cut tag found insid	ter attached de the bus.	d nearby	driver.	_		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:						
	Approved						Approved							
	Not Approved						Not Approved							
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:							
Badge No Date					Badge	e No			Date					
Signa	Signature of District Official													
											TD 4	I3 Povice	ed 11/04	
						1					1 K-1	O MEVIS	5u 11/U4	



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highway Patrol as soon as all defects are corrected.													
Instru	ictions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	er in serv	ice. Ple	ease d	elete it fr	om OPI	's records.						
Ple	ase make corrections noted below. Don't	black ou	ut the er	ror, OF	Pl may ne	ed to re	ead it to make the corr	ection.					
OPI C	County # and County Name					Distri	ct Name						
	07 Cascade						Cro	at Falls P	ublia S	Soble			
Vehic	le I.D. # (VIN) - Entire Number		Mo	del Ye	ar	Licen		at rails r	Rated C		, ****		
Verilo	ie i.D. # (VIIV) - Littlie Number		IVIC	uerre	aı	Licen	3 <del>C</del> #		Nateu	Japacity			
	1GBL6P1B2KV112345			198	9		8516				71		
Chass	sis Make			E	Body Mak	е		Bus Type:	: (see ? f	or defini	ition)		
	Chevrolet					14	/ard	$\Box$ A $\Box$	⊒в [	<b>✓</b> C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	· Lift F	quipped?		raru						
					٠								
☐ Ye			orwar					ot Applica					
Туре	of Fuel:	Is B	us:	Distri	ct Owned	<b>✓</b> C	ontractor Owned If co	ontractor ow	ned, con	tractor's	name	is:	
□G	as □ Diesel ☑ Other						Big Sky Bus	Linos					
Dig Oky Dus Eines													
INSPECTION  TO BE FILLED OUT BY THE HIGHWAY PATROL													
This inspection is for:  1st semester  2nd semester													
Inis inspection is for: ✓ 1st semester													
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standar	ds	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus	es in Monta	na			**	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior					<u> </u>	
C18	Turn signal lamps - front					C21	Seating					<u> </u>	
C18	Turn signal lamps - side (post 1987)					C14	Floor					<del> </del>	
C18	Red amber signals - front  Marker lamps - front					C9 C22	Aisle Storage					_	
C18	Windshield				+	C24	Tools - storage Windows					+	
C24	Windshield wipers					C13	Warning device					+	
C20	Exterior mirrors					C13	Buzzer emergency de	oor				+	
C3	Battery					C12	Emergency door					1	
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps					<u> </u>	
C6	Horn					C18	Marker lamps - rear						
C20 C6	Interior mirror					C19 C17	Strobe light - rear *** Identification - rear					_	
C2	Speedometer Brakes				+	C17	Exhaust system (no l	oake)				+	
C21	Driver seat belt	1			+	C5	Fuel tank	canoj				+-	+
C7	Steering gear				1	C7	Tires (2/32" rear - 4/3	2" front min	.)			1	
C13	Fire extinguisher (5 lbs)	1	1				Cleanliness		•			1	
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	_				—	
C6	Heaters						Shovel (securely fast					₩	
*Bago pi	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in I	Montana	(2002 E4	tion\ *	***Buc driv	ore are i	Axe (securely fastene		tor attacho	d poarby	drivor		
	umber reference, Standards for School Buses in i not apply. ***New buses ordered after 08/15/02.*'										unver.		
					-								
	st inspection, this bus is: Approved						einspection, this bus Approved	13.					
	Not Approved						Not Approved						
	Inspecting Patrol Officer:						cting Patrol Officer:						
mapet	mapeoung i auto Officer.					ape							
Badge	No.	Date				Badge	e No			Date			
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correct	ted.	20 .0	, .							0100 2)	0	
	actions to OPI from School District: s bus has been sold, retired, or is no longe		ice. Ple	ase d	elete it fr	om OPI	's records.						
	ease make corrections noted below. Don't							ection.					
OPI C	County # and County Name					Distri	ct Name						
	07 Cascade						Gro	at Falls I	Dublic 9	Schle			
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Ye	ear	Licen		at i alis i	Rated C		, ****		
	,				_					,			
Chan	1GBL6P1B5KV111741 sis Make			198			8515	Rue Type	: (soo 2 fe	or dofini	71		
Chas	sis iviakė			'	Body Mak								
Chevrolet							/ard	$\Box$ A	В	✓ C	$\sqcup$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?								
☐ Ye	es 🗹 No	□ F	orward	l Fad	cing [	☐ Aisl	e Facing 🔛 🗹 N	ot Applica	able				
Туре	of Fuel:	ls Bu	IS:	Distri	ct Owned	<b>✓</b> C	ontractor Owned If co	ontractor ov	vned, cont	tractor's	name	is:	
$\Box$ G	as □ Diesel ☑ Other						Big Sky Bus	Lines					
					INCDE	CTION	Dig Oky Dus	LIIICS					
INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL													
	This	inspecti				t semes		ster					
			Appro	ved							Арр	roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in to			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior					<u> </u>	
C18	Turn signal lamps - front					C21	Seating					<del> </del>	<u> </u>
C18	Turn signal lamps - side (post 1987)  Red amber signals - front					C14 C9	Floor Aisle					<del> </del>	+
C18	Marker lamps - front					C22	Tools - storage						1
C18	Windshield					C24	Windows					1	
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					-
C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer						Identification - rear					1	
C2	Brakes					C4	Exhaust system (no le	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	า.)				
C13	Fire extinguisher (5 lbs)					000	Cleanliness					<u> </u>	
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch					1	
C13	Defroster					CS	Required by forest r	equiation:					
C6	Heaters						Shovel (securely faste	_					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
	umber reference, Standards for School Buses in Into apply. ***New buses ordered after 08/15/02.**										driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
☐ Not Approved							Not Approved						
Inspec	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge No. Date					Badge				Date				
Signa	Signature of District Official												
											TR-1	3 Revise	ed 11/04



#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.									
Please make corrections noted below. Don't bla	ack out the error, 0	OPI may need	d to read it to make the corre	ection.					
OPI County # and County Name			District Name						
07 Cascade		Great Falls Public Schls							
Vehicle I.D. # (VIN) - Entire Number	Model \	Year	License #		Rated Capacity *****				
1GBL6P1B6KV111523	19	989	8523		71				
Chassis Make		Body Make		Bus Type: (see ? for definition)					
Chevrolet			Ward	$\Box$ A	□B ☑C □D				
Wheel Chair Lift Equipped?	Wheel Chair Lift	Equipped?							
☐ Yes    ✓ No	☐ Forward Fa	acing $\Box$	Aisle Facing ✓ N	ot Applica	able				
Type of Fuel:	Is Bus: Dist	trict Owned	Contractor Owned If co	ntractor ov	vned, contractor's name is:				
☐ Gas ☐ Diesel ☑ Other	Big Sky Bus Lines								
INSPECTION									

#### TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ✓ 1st semester ☐ 2nd semester

Approved

			Approved								
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. \*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:					
Approved		Approved					
Not Approved		Not Approved					
Inspecting Patrol Officer:		Inspecting Patrol Officer:					
Badge No.	Date	Badge No.	Date				
Signature of District Official		Date					



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	Highway Patrol as soon as all defects are corrected.												
	Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, O	PI may ne	eed to re	ead it to make the corre	ection.					
OPI C	County # and County Name					Distri	ct Name						
	07 Cascade						Gre	at Falls F	Public S	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Y	ear	Licen		at i ano i	Rated C		****		
·							_			,			
1GBL6P1BXKV111525 1989							8518	D T	( 0.1		71		
Chassis Make Body Make						ке		Bus Type	,		•		
	GMC					Ward □ A □ B ☑ C □ D							
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?								
□ Ye	es 🗹 No		orward	ط Fa	cina	Δiel	e Facing <b>☑</b> N	ot Applica	ahla				
		_											
• •	of Fuel:	IS B	us:	DIST	ct Owned	V C	ontractor Owned If co	ontractor ow	mea, com	ractor s	name	S:	
$\Box$ G	as 🗌 Diesel 🗹 Other						Big Sky Bus	Lines					
INSPECTION													
TO BE FILLED OUT BY THE HIGHWAY PATROL													
This inspection is for: ✓ 1st semester ☐ 2nd semester													
			Appr								App	roved	
Page	Items listed in the Standards	Yes	No	NA **	Corr	Page	Items listed in			Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		ana			**	↓
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps	1			_	C18	Interior lamps					—	+
C10	Color Turn signal lamps - front					C18 C21	Ceiling - interior						+
C18	Turn signal lamps - front  Turn signal lamps - side (post 1987)	<del> </del>				C14	Seating Floor					┼─	+
C18	Red amber signals - front				+	C9	Aisle					+	+
C18	Marker lamps - front					C22	Tools - storage					<del>                                     </del>	+
C18	Windshield	1			+	C24	Windows				1	<del>                                     </del>	+
C24	Windshield wipers					C13	Warning device					1	
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear				<u> </u>	
C6	Head lamp indicator					C18	Stop lamps						
C6 C20	Horn Interior mirror	<u> </u>				C18	Marker lamps - rear Strobe light - rear ***					<del> </del>	
C20	Speedometer	<del> </del>				C19 C17	Identification - rear					┼─	+
C2	Brakes					C4	Exhaust system (no l	eaks)				<del>                                     </del>	+
C21	Driver seat belt					C5	Fuel tank	canoj					+
C7	Steering gear	1				C7	Tires (2/32" rear - 4/3	2" front mir	า.)				+
C13	Fire extinguisher (5 lbs)						Cleanliness		,				
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r					<b>↓</b>	—
C6	Heaters						Shovel (securely fast					<u> </u>	
C20	Wheelchair forward facing (post 1993)	4	(0000 F-II)	· \	*****		Axe (securely fastene			-1	alab ca a	<u> </u>	
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**										ariver.		
			3		, ,,,,,,								
	st inspection, this bus is:						einspection, this bus	is:					
	Approved Not Approved						Approved Not Approved						
						_							
mspec	Inspecting Patrol Officer:						cting Patrol Officer:						
Badge No Date					Badge	e No			Date				
Signa	ure of District Official					Date							



Inspecting Patrol Officer:

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBL6P1BXKV112352 1989 8543 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Ward Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas Diesel ✓ Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved

Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBL6P1P4MV100213 1991 8528 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Ward Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date

Badge No.

Date

Date

Date



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.											
	actions to OPI from School District: s bus has been sold, retired, or is no longe		rice. Ple	ase (	delete it fr	om OPI	's records.						
☐ Ple	ase make corrections noted below. Don't	black ou	it the err	or, O	PI may ne	ed to re	ead it to make the corre	ection.					
OPI County # and County Name					District Name								
	07 Cascade						Grea	at Falls F	Public S	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen	se#		Rated C	Capacity	****		
	1CDL6D1DVM\/100202			19	01		8527				72		
Chas	1GBL6P1PXMV100202 sis Make				Body Mal	<u> </u>	0321	Bus Type	· (see ? fo	or defini	72		
Cilas	ois iviane				Dody Mar	.C		, ,	`		,		
	Chevrolet						/ard	□ A [	☐ B	✓ C			
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	Equipped?	1							
□ Ye	es 🗹 No		orward	d Fa	cina	☐ Aisl	e Facing 🗹 N	ot Applica	able				
Type	of Fuel:	-					ontractor Owned If co			tractor's	name i	s:	
• •									,				
□G	as   Diesel   Other						Big Sky Bus	Lines					
INSPECTION													
							GHWAY PATROL						
	This inspection is for:												
D	the sea l'atant's the Oten dende	1./	Appro			D	Drawe Parad Sa	d Otalada		1/		roved	10
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in to for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach					<del>                                     </del>	+
C18	Head lamps					C18	Interior lamps	-					+
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows					<b>└</b>	<u> </u>
C24	Windshield wipers					C13	Warning device					<u> </u>	
C20	Exterior mirrors					C13	Buzzer emergency do	oor				<b>↓</b>	+
C3 C4	Battery Generator or alternator					C12 C18	Emergency door Red amber signals -	roor				<del>                                     </del>	+
C11	Service door	+				C18	Turn signal lamps - re					┼─	+
C6	Head lamp indicator					C18	Stop lamps	zai				+	+
C6	Horn					C18	Marker lamps - rear						+
C20	Interior mirror	1				C19	Strobe light - rear ***						+
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no le	eaks)					
C21	Driver seat belt					C5	Fuel tank					<b>└</b>	<u> </u>
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	า.)			<u> </u>	
C13	Fire extinguisher (5 lbs)	-				000	Cleanliness					<del> </del>	
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch					+	+
C11	Defroster Defroster					C3	Required by forest r	equiation:				<del>                                     </del>	+
C6	Heaters						Shovel (securely faste					<del>                                     </del>	+
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**						equired to wear lap/should	der belts - cut			driver.		
On fi	st inspection, this bus is:					On ro	einspection, this bus	ie.					
	Approved						Approved						
	Not Approved						Not Approved						
	eting Patrol Officer:						cting Patrol Officer:						
	No	Date				Badge No Date							
Signa	ture of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBL6P1VXKV111752 1989 8541 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Ward Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas Diesel ✓ Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBL7T1C21J508425 2002 E141 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **GMC Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

riigiiw	ay Fatiol as soon as all delects are correc	.cu.											
Instru	ictions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ase	delete it fr	om OPI'	's records.						
☐ Ple	ase make corrections noted below. Don't	black ou	at the erro	or, O	PI may ne	eed to re	ead it to make the corre	ection.					
OPI County # and County Name					District Name								
	•												
	07 Cascade						Grea	at Falls F					
Vehic	le I.D. # (VIN) - Entire Number		Mod	lel Y	'ear	Licen	se#		Rated C	Capacity	****		
	4CDI 7T4 I7V I44 4007			40	.00		4077				40		
Chan	1GBL7T1J7VJ114827			19	98		1677	Bus Type	: (000 2 f	or dofini	48		
Chas	sis Make				Body Mal	ke		bus Type	•		,		
	Chevrolet					Blu	ebird	$\square$ A	□ B	✓ C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift [	Equipped?								
	N-					¬ ∧:-ı	. F	. 4 . A !	-1-1-				
✓ Y		<u> </u>	orward					ot Applica					
Type	of Fuel:	Is B	us:	Distr	rict Owned	l 🗸 C	ontractor Owned If co	ntractor ow	ned, con	tractor's	name	is:	
$\Box$ G	as ☑ Diesel ☐ Other						Dia Clar Dua	1:					
							Big Sky Bus	Lines					
						CTION							
							GHWAY PATROL						
	This	inspect	ion is for		<b>✓</b> 1s	t semes	ster 2nd semes	ster					
			Appro	ved							Арр	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t			Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		ına			**	
C17	Identification - front					C34	Belt cutter **** attache	ed					
C18	Head lamps					C18	Interior lamps					<b>↓</b>	
C10	Color					C18	Ceiling - interior					<b>↓</b>	
C18	Turn signal lamps - front					C21	Seating					<b>↓</b>	<u> </u>
C18	Turn signal lamps - side (post 1987)					C14	Floor					<b>↓</b>	<u> </u>
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device					—	
C20	Exterior mirrors					C13	Buzzer emergency do	oor				<b>├</b>	
C3	Battery					C12	Emergency door					+	_
C4 C11	Generator or alternator					C18	Red amber signals -					<b>├</b> ──	-
C6	Service door Head lamp indicator					C18	Turn signal lamps - re Stop lamps	aı				+-	-
C6	Horn	1				C18	Marker lamps - rear					+	+
C20	Interior mirror					C19	Strobe light - rear ***					+-	+
C6	Speedometer					C17	Identification - rear					+	+
C2	Brakes	1				C4	Exhaust system (no le	eaks)				+	+
C21	Driver seat belt					C5	Fuel tank	ouno,					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	n.)			+	+
C13	Fire extinguisher (5 lbs)						Cleanliness		/			+	+
C13	First aid kit					C22	Stop arm					1	
C13	Body fluids kit					C5	No trailer hitch					1	
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely faste	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	ed)				1	1
	umber reference, Standards for School Buses in I										driver.		
**Does r	not apply. ***New buses ordered after 08/15/02.*	***Basec	l on origina	al cap	pacity listed	on the m	anufacturers certification to	ag found insi	de the bus.				
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
ope						ope							
Badge	No	Date				Badge	No			Date			
Signa	ture of District Official					Date							
**													



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

School Year 2006 Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBL7T1P7WJ111111 1999 8540 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird** Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.

Date

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correct	ed.											
Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
Ple	ease make corrections noted below. Don't	black ou	it the erro	r, O	PI may ne	ed to re	ead it to make the corre	ection.					
OPI County # and County Name					District Name								
	07 Cascade						Grea	at Falls F	Public S	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Mod	el Y	'ear	Licen				Capacity	****		
	1GBM6P1P2MV100702			19	91		D835				71		
Chas	sis Make		•	Ť	Body Mal	е		Bus Type	e: (see ? f	or defini			
	Chevrolet					DI.	ıebird	$\square$ A	□в	<b>✓</b> C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair L	ift E	Equipped?		lebila						
□ Y			orward				e Facing <b>☑</b> N	ot Applie	abla				
	of Fuel:	-						ot Applica		traatarla	2020	in.	
• •		IS DI	us: 💹 🖸	JISII	ict Owned	<b>V</b> C	ontractor Owned If co	miracior ov	vnea, con	illactors	name	S.	
<b>✓</b> G	as 🗌 Diesel 🗌 Other						Big Sky Bus	Lines					
					_	CTION							
	<del>_</del>			.ED			GHWAY PATROL						
	This	inspect	ion is for:	vod.		t semes	ster 2nd semes	ster			۸nn	royad	
Page	Items listed in the Standards	Yes	Appro No 1	vea NA	Corr	Page	Items listed in	the Standa	rds	Yes	No No	roved NA	Corr
No.*	for School Buses in Montana	100		*	00	No.*	for School Bus			. 55	110	**	00.1
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps					Ļ	╀
C10	Color					C18	Ceiling - interior					₩	<del> </del>
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)					C21 C14	Seating Floor					├	+
C18	Red amber signals - front					C14	Aisle					$\vdash$	+
C18	Marker lamps - front					C22	Tools - storage					+	+
C18	Windshield					C24	Windows						†
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door					<u> </u>	
C4	Generator or alternator					C18	Red amber signals -					—	
C11	Service door					C18 C18	Turn signal lamps - re	ear				┼	+
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					$\vdash$	+
C20	Interior mirror					C19	Strobe light - rear ***					_	+
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no le	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	n.)			<del>                                     </del>	—
C13	Fire extinguisher (5 lbs)					Coo	Cleanliness					┼	+
C13	First aid kit  Body fluids kit					C22 C5	Stop arm No trailer hitch					$\vdash$	+
C11	Defroster					00	Required by forest r	egulation:				+	+
C6	Heaters						Shovel (securely faste					†	
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	ed)					
	umber reference, Standards for School Buses in Not apply. ***New buses ordered after 08/15/02.**										driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	e No	Date				Badge No Date							
Signa	ture of District Official					Date						· <u></u>	
											ΓR-1	3 Revis	ed 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.											
Instructions to OPI from School District:													
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
☐ Ple	ase make corrections noted below. Don't	PI may ne	need to read it to make the correction.										
OPI County # and County Name					District Name								
27.0						0	ot Falla D		Salala.				
Vohio	le I.D. # (VIN) - Entire Number		Me	del Ye	or	Licen		at Falls P	Rated C		, ****		
venic	ie i.D. # (VIN) - Entire Number		IVIC	idei re	ai	Licen	se #		Raied	apacity			
	1GBM6P1P6MV100704			199	1		D834				71		
Chas	sis Make			E	Body Mak	е		Bus Type:	(see ? fo	or defini	ition)		
	Chevrolet					DI.	ebird	$\Box$ A $\Box$	В	<b>✓</b> C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chai	r Lift F	quipped?		lebira						
					٠								
☐ Ye			orwar					ot Applica					
Туре	of Fuel:	Is B	us:	Distric	ct Owned	<b>✓</b> C	ontractor Owned If co	ontractor owr	ned, con	tractor's	name	s:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					111000	OTION	Dig Oky Dus	LIIICS					
INSPECTION  TO BE FILLED OUT BY THE HIGHWAY PATROL													
TO BE FILLED OUT BY THE HIGHWAY PATROL  This inspection is for: ✓ 1st semester ☐ 2nd semester													
		Поросс		oved	<u>.</u> .0	. 0011100	2114 001110	5101			qqA	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standard	ds	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		na			**	
C17	Identification - front					C34	Belt cutter **** attach	ed				<u> </u>	
C18	Head lamps					C18	Interior lamps					<b>↓</b>	
C10	Color	1			-	C18	Ceiling - interior					—	
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)					C21 C14	Seating Floor					<b>├</b> ──	
C18	Red amber signals - front					C9 Aisle						╁	
C18	Marker lamps - front					C22 Tools - storage							
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door					<u> </u>	
C4	Generator or alternator					C18	Red amber signals -					<u> </u>	
C11 C6	Service door					C18	Turn signal lamps - re	ear				<del> </del>	
C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					┼─	
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.	)			Ļ	
C13	Fire extinguisher (5 lbs)					000	Cleanliness						
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch					├──	
C11	Defroster Defroster					CO	Required by forest r	equilation:				$\vdash$	
C6	Heaters						Shovel (securely fast	_					
C20	Wheelchair forward facing (post 1993)	1			1		Axe (securely fastene					<del>                                     </del>	
*Page n	umber reference, Standards for School Buses in I						equired to wear lap/should	der belts - cutt			driver.		•
**Does r	not apply. ***New buses ordered after 08/15/02.**	****Basec	l on origir	nal capa	city listed	on the m	anufacturers certification t	ag found insid	e the bus.				
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	eting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge No. Date							
	ture of District Official					Date							
Jigila						2410							



Date

Signature of District Official

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Date

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GDG7T1PZYJ516848 1998 1070 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ✓ Forward Facing ☐ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.										
Instructions to OPI from School District:												
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
Please make corrections noted below. Don't black out the error, OPI may ne						ed to read it to make the correction.						
OPI C	County # and County Name					Distri	ct Name					
	07 Cascade						Gre	at Falls Pub	olic Schle	;		
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen			ated Capaci			
	400 10040004540504			400			0500					
01	1GDJ6P1B0GV510594			198		<u> </u>	8530	Dua Turan (a.	aa O far dafi	71		
Chas	sis Make				Body Mal	Се		Bus Type: (s		,		
	GMC					W	/ard	□ A □ I	B <b>✓</b> C	$\sqcup$ D		
Whee	l Chair Lift Equipped?	Whe	el Chai	r Lift Ed	quipped?	)						
☐ Ye	es 🗹 No		orwar	d Fac	ina	Aisl	e Facing 🔽 N	ot Applicable	e.			
	of Fuel:	Is B					ontractor Owned If co			's name	ie.	
		13 0	us	Distric	or Owner	• •	ontractor Owned in co	ontractor owner	a, contractor	3 Harric	13.	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines				
					INSPE	CTION						
					OUT BY	THE HI	GHWAY PATROL					
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ster 2nd seme	ster				
	B	Tv.	<del>, ''</del>	roved	10	I 5	I 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1,,		proved	10
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus		Yes	No	NA **	Corr
C17	Identification - front				+	C34	Belt cutter **** attach				-	
C18	Head lamps					C18	Interior lamps	Cu			+	
C10	Color					C18	Ceiling - interior					
C18	Turn signal lamps - front					C21	Seating					
C18	Turn signal lamps - side (post 1987)					C14	Floor					
C18	Red amber signals - front					C9	Aisle					
C18	Marker lamps - front					C22 Tools - storage		_	<del>                                     </del>			
C18	Windshield					C24	Windows					
C24 C20	Windshield wipers  Exterior mirrors					C13	Warning device					
C3	Battery				+	C12	Buzzer emergency do Emergency door	501			+-	
C4	Generator or alternator					C18	Red amber signals -	rear			+	
C11	Service door				†	C18	Turn signal lamps - re			1	+	
C6	Head lamp indicator					C18	Stop lamps					
C6	Horn					C18	Marker lamps - rear					
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer					C17	Identification - rear					
C2	Brakes	1			<u> </u>	C4	Exhaust system (no l	eaks)		_	+	
C21	Driver seat belt Steering gear				+	C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front min )		+	+-	1
C13	Fire extinguisher (5 lbs)				+	O1	Cleanliness	2 11011(111111.)		+	+	
C13	First aid kit				1	C22	Stop arm				+	
C13	Body fluids kit					C5	No trailer hitch					
C11	Defroster						Required by forest r	egulation:				
C6	Heaters						Shovel (securely fast					
C20	Wheelchair forward facing (post 1993)				1		Axe (securely fastene			1,		
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**									oy driver.		
					,				'			
	rst inspection, this bus is:					On re	einspection, this bus Approved	is:				
	Approved Not Approved						Not Approved					
	cting Patrol Officer:					Insper	cting Patrol Officer:					
spec						spe						
Badge	• No	Date				Badge	e No		Date			
Signa	ture of District Official	-				Date						



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1B1KV514971 1989 8533 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name **District Name Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GDJ6P1B1KV520317 1989 C554 71 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A □В ✓ C  $\Box$  D Ward **GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing ☐ District Owned ✓ Contractor Owned If contractor owned, contractor's name is: Type of Fuel: ✓ Gas Diesel Other Big Sky Bus Lines **INSPECTION** TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front	1			1	C34	Belt cutter **** attached				†
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:				
Approved		Approved				
Not Approved		Not Approved				
Inspecting Patrol Officer:		Inspecting Patrol Officer:				
Badge No.	Date	Badge No.	Date			
Signature of District Official		Date				



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highway Patrol as soon as all defects are corrected.													
Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
Please make corrections noted below. Don't black out the error, OPI may no													
OPI County # and County Name						ct Name							
	07 Cascade						Gre	at Falls Pub	lic Schle				
Vehic	le I.D. # (VIN) - Entire Number		Мс	del Ye	ar	Licen			ated Capacit	y ****			
	4.00 1004 0051/000040			400			0504			74			
Chan	1GDJ6P1B2FV620643 sis Make			198	Sody Mal	· •	8521	Bus Type: (se	oo 2 for dofin	71			
Crias	sis iviakė			-	ouy war	(e		, ,					
	GMC						/ard		3 <b>⊻</b> C	$\sqcup$ D			
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped?	)							
☐ Ye	es 🗹 No		orwar	d Fac	ing [	☐ Aisl	e Facing 🗹 N	ot Applicable	Э				
Туре	of Fuel:	Is B	us:	Distric	ct Owned	<b>✓</b> C	ontractor Owned If co			s name	is:		
□G	as □ Diesel ☑ Other					_							
	as Diesei 🗹 Othei						Big Sky Bus	Lines					
					_	CTION							
							GHWAY PATROL						
	Inis	inspect		r: roved	<b>✓</b> 1s	t semes	ster 2nd seme	ster		۸nn	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus				**	00	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)  Red amber signals - front					C14 C9	Floor Aisle						
C18	Marker lamps - front					C22 Tools - storage			+				
C18	Windshield					C24 Windows							
C24	Windshield wipers				1	C13	Warning device			1			
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank	Í					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)					
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit  Defroster					C5	No trailer hitch  Required by forest r	ogulation:					
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993)	†	1		†		Axe (securely fastene			†	†		
*Page ni	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**						equired to wear lap/shoul	der belts - cutter a		y driver.		4	
	rst inspection, this bus is:						einspection, this bus						
	Approved						Approved	13.					
	Not Approved						Not Approved						
	eting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge No. Date							
	ture of District Official	· · · =				Date							
3													



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Trighway Fattor as soon as an defects are corrected.												
Instru	ictions to OPI from School District:											
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
Please make corrections noted below. Don't black out the error, OPI may ne												
OPI County # and County Name						Distri	ct Name					
0	really in all a county traine					2.0	ot 110					
	07 Cascade						Grea	at Falls Public	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen	se#	Rated	Capacity	/ ****		
	1GDJ6P1B2HV526622			19			8505			12		
Chas	sis Make				Body Mal	ке		Bus Type: (see ?	for defin	ition)		
	GMC					١٨/-	ayne	$\Box$ A $\Box$ B	✓ C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	l ift F	Equipped?		ayıı <del>c</del>					
✓ Y	es 🗆 No		orward	l Fa	cing	<b>⊻</b> Aisl	e Facing 🔲 No	ot Applicable				
Туре	of Fuel:	Is B	us:	Distri	ict Owned	I ✓ C	ontractor Owned If co	entractor owned, co	ntractor's	name	is:	
	as □ Diesel ☑ Other											
□G	as 🗆 Diesei 🛂 Othei						Big Sky Bus	Lines				
					INSPE	CTION						
		TC	BE FIL	LED	<b>OUT BY</b>	THE HI	GHWAY PATROL					
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd semes	ster				
			Appro	oved						App	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t	the Standards	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Buse	es in Montana			**	
C17	Identification - front					C34	Belt cutter **** attache	ed				
C18	Head lamps					C18	Interior lamps					
C10	Color					C18	Ceiling - interior					
C18	Turn signal lamps - front					C21	Seating					
C18	Turn signal lamps - side (post 1987)					C14	Floor					
C18	Red amber signals - front					C9	Aisle					
C18	Marker lamps - front					C22 Tools - storage						
C18	Windshield					C24	Windows					
C24	Windshield wipers					C13	Warning device					
C20	Exterior mirrors					C13	Buzzer emergency do	oor				
C3	Battery					C12	Emergency door					
C4	Generator or alternator					C18	Red amber signals -	rear				
C11	Service door					C18	Turn signal lamps - re	ear				
C6	Head lamp indicator					C18	Stop lamps					
C6	Horn					C18	Marker lamps - rear					
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer					C17	Identification - rear					
C2	Brakes					C4	Exhaust system (no le	eaks)				
C21	Driver seat belt					C5	Fuel tank	•				
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness	·				
C13	First aid kit					C22	Stop arm					
C13	Body fluids kit					C5	No trailer hitch					
C11	Defroster						Required by forest r	egulation:				
C6	Heaters						Shovel (securely faste	ened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	ed)				
*Page n	umber reference, Standards for School Buses in I	Montana (	(2002 Edit	ion).	****Bus dri	vers are r	equired to wear lap/should	der belts - cutter attacl	hed nearby	driver.		
**Does r	not apply. ***New buses ordered after 08/15/02.**	***Based	d on origina	al cap	acity listed	on the m	anufacturers certification to	ag found inside the bu	JS.			
On fi	rst inspection, this bus is:					On re	inspection, this bus	is:				
	Approved						Approved					
	Not Approved						Not Approved					
Inspecting Patrol Officer:						cting Patrol Officer:						
mape						mapet	Jung I au 01 01110er.					
Badge	No.	Date				Badge No Date						
	ture of District Official					Date						
5 -												



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

	nstructions to OPI from School District:											
This bus has been sold, retired, or is no longer in service. Please delete it from Please make corrections noted below. Don't black out the error, OPI may nee							ction					
	County # and County Name	bidok ot		01, 01	Tillayin	District Name						
	07 Canada					Croot Follo Bublic Coble						
Vobio	le I.D. # (VIN) - Entire Number		I Mo	del Ye	or	Great Falls Public SchIs  License # Rated Capacity *****						
Verilo	ie i.D. # (VIIV) - Littlie Numbei		IVIO	uerre	aı	Rated Capacity						
	1GDJ6P1B2KV514879			198			8509			66		
Chas	sis Make			[	Body Mal	ke		Bus Type: (see ?				
	GMC					Car	penter	$\square$ A $\square$ B	✓ C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?	?						
☐ Y	es 🗹 No		orwar	d Fad	cing	☐ Aisl	e Facing 🗹 No	t Applicable				
Туре	of Fuel:	Is B					ontractor Owned If con		ntractor's	name	is:	
✓ G												
<b>V</b> G	as 🗆 Diesei 🗀 Otilei						Big Sky Bus l	Lines				
					_	CTION						
	Thio						GHWAY PATROL	0.5				
	inis	inspeci	tion is foi Appr		<b>▼</b> 18	t semes	ster 2nd semest	er		Δnr	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in th	ne Standards	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Buses				**	
C17	Identification - front					C34	Belt cutter **** attached	d				
C18	Head lamps					C18	Interior lamps				1	
C10 C18	Color Turn signal lamps front					C18 C21	Ceiling - interior				+	
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)					C21	Seating Floor				+	
C18	Red amber signals - front					C9	Aisle					
C18	Marker lamps - front					C22	Tools - storage					
C18	Windshield					C24	Windows					
C24	Windshield wipers					C13	Warning device					
C20	Exterior mirrors					C13	Buzzer emergency doc	or			-	
C3 C4	Battery Generator or alternator					C12 C18	Emergency door Red amber signals - re	nor.			+	
C11	Service door					C18	Turn signal lamps - rea					
C6	Head lamp indicator					C18	Stop lamps	41				
C6	Horn					C18	Marker lamps - rear					
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer					C17	Identification - rear					
C2	Brakes		1			C4	Exhaust system (no lea	aks)				
C21	Driver seat belt Steering gear		1			C5 C7	Fuel tank Tires (2/32" rear - 4/32	" front min )				+
C13	Fire extinguisher (5 lbs)					01	Cleanliness	mont min.)				
C13	First aid kit					C22	Stop arm					
C13	Body fluids kit					C5	No trailer hitch					
C11	Defroster						Required by forest re	gulation:				
C6	Heaters						Shovel (securely faster				-	
*Page n	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in N	Montana	(2002 Edi:	tion) *	***Bue dri	vers are	Axe (securely fastened	,	hed nearby	driver		
	not apply. ***New buses ordered after 08/15/02.**									unven.		
	rst inspection, this bus is:		-				einspection, this bus is					
	Approved						Approved	<b>.</b>				
Not Approved					Not Approved							
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:					
-	Badge No. Date				Badge No. Date							
	ture of District Official	_				Date						
										TR-	13 Revis	ed 11/04



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

nigriw	ay Patrol as soon as all defects are correcte	u.											
Instru	Instructions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longer	om OPI	's records.										
Please make corrections noted below. Don't black out the error, OPI may nee													
	County # and County Name				-	District Name							
						-10.11							
07 Cascade							Gre	at Falls P					
Vehic	le I.D. # (VIN) - Entire Number	-	Mod	lel Y	'ear	Licen	se #		Rated C	Capacity	****		
	1CD ICD1P2VVE44022			40	.00		0467				ee.		
Chas	1GDJ6P1B2KV514932				<b>89</b> Body Mak	<u> </u>	8467	Bus Type:	(SAA 2 f	or defini	66		
Chassis Make Body Mak						æ		, ,	•		′		
GMC					Car	penter	$\Box$ A	□ B	<b>✓</b> C	$\Box$ D			
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift I	Equipped?								
☐ Ye	es 🗹 No	l □ ₽	orward	۱F۵	acina [	Δiel	e Facing <b>☑</b> N	ot Applica	hle				
3									44l -				
Туре	or Fuer.	Is Bu	JS:	DIST	nct Owned	V C	ontractor Owned If co	ontractor ow	nea, con	tractor s	name	S:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION	<u> </u>						
		TC	BE FII	LED	_	-	GHWAY PATROL						
	This i					t semes		ster					
This inspection is for: ✓ 1  Approved								- · <del>- ·</del>			aqA	roved	
Page	Items listed in the Standards	Yes		NA	Corr	Page	Items listed in	the Standar	ds	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus					**	
C17	Identification - front					C34	Belt cutter **** attach	ied					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating			ļ			
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle			1		<u> </u>	
C18	Marker lamps - front Windshield		<b>-</b>		-	C22 C24	Tools - storage Windows					<del>                                     </del>	1
C18	Windshield wipers		+		+	C24	Warning device						
C20	Exterior mirrors		<del>                                     </del>			C13	Buzzer emergency do	nor		1			
C3	Battery		<del>                                     </del>		+	C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re						
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer				$\bot$	C17	Identification - rear					<u> </u>	
C2	Brakes					C4	Exhaust system (no l	eaks)		-		ļ	
C21	Driver seat belt					C5	Fuel tank	20" front mi-	. \				
C7 C13	Steering gear Fire extinguisher (5 lbs)		<del>                                     </del>		-	C7	Tires (2/32" rear - 4/3 Cleanliness	o∠ HUHLHIIN	.)	1	1	}	1
C13	First aid kit		<del>                                     </del>		-	C22	Stop arm			1			
C13	Body fluids kit					C5	No trailer hitch			<del>                                     </del>	<del>                                     </del>		
C11	Defroster						Required by forest r	regulation:		1	<del>                                     </del>		
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
*Page ni	umber reference, Standards for School Buses in M										driver.		
"Does r	not apply. ***New buses ordered after 08/15/02.***	based	on origina	ıı cap	Dacity listed	on the m	anuracturers certification t	iag tound insid	ie tnė bus	·			
On fir	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspec	eting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge No. Date					Bado	e No.			Date				
	Badge No Date Signature of District Official												
Signal	and of District Official					Date							
											TD 4	2 Devile	nd 11/04
						1					ı K-1	J KEVIS	ed 11/04



Inspecting Patrol Officer:

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1B2KV515594 1989 8507 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ☐ Forward Facing ✓ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved

Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Date

Signature of District Official

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1B3KV514678 1989 8512 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1B4KV514852 1989 8466 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	Highway Patrol as soon as all defects are corrected.												
Instru	Instructions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Pl	ease de	elete it fr	om OPI	's records.						
☐ Ple	ease make corrections noted below. Don't	black ou	ıt the er	ror, OP	'I may ne	eed to read it to make the correction.							
OPI (	County # and County Name					Distri	ct Name						
	07 Cascade						Gro	at Falls P	uhlia S	chla			
Vehic	le I.D. # (VIN) - Entire Number		Mc	del Ye	ar	Licen		at Falls F	Rated C		, ****		
· · ·					Liocii	30 II		rated 0	apaony				
	1GDJ6P1B4KV514964			<u> 198</u>			8534				66		
Chas	sis Make			B	ody Mal	ке		Bus Type:	: (see ? fo	or defini	ition)		
GMC					Carı	penter	$\Box$ A	□в 🤄	✓ C	$\Box$ D			
Wheel Chair Lift Equipped? Wheel Chair Lift Equipped?						<del></del>							
□ Y	es 🗹 No	$  \Box $	orwar	d Fac	ina	Δiel	e Facing 🔽 N	ot Applica	hle				
	of Fuel:						ontractor Owned If co			rootor'o	nomo	io:	
		18 00	us	DISTIL	t Owner	<b>V</b> C	ontractor Owned in co	Jilliacioi ow	neu, com	iacioi s	i ilallie i	ъ.	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION							
							GHWAY PATROL						
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ster 2nd seme	ster					
				roved	1_							roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach		iiu .			+	+
C18	Head lamps					C18	Interior lamps					<del>                                     </del>	+
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21 Seating							
C18	Turn signal lamps - side (post 1987)					C14 Floor					Ь—		
C18	Red amber signals - front	<u> </u>				C9 Aisle C22 Tools - storage					₩	<del> </del>	
C18	Marker lamps - front Windshield	<u> </u>				C24 Windows					+	+	
C24	Windshield wipers					C13 Warning device						+	+
C20	Exterior mirrors					C13	Buzzer emergency de	oor					†
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear				—	
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					┼	_
C20	Interior mirror					C19	Strobe light - rear ***					+-	+
C6	Speedometer						Identification - rear					<del>                                     </del>	+
C2	Brakes					C4	Exhaust system (no l	eaks)				†	
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min	.)			Ь—	
C13	Fire extinguisher (5 lbs)	<u> </u>				000	Cleanliness					₩	<del> </del>
C13	First aid kit Body fluids kit	<u> </u>				C22 C5	Stop arm No trailer hitch					+-	+
C11	Defroster					00	Required by forest i	regulation:				+	+
C6	Heaters						Shovel (securely fast	_				†	1
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	ed)					
	umber reference, Standards for School Buses in l not apply. ***New buses ordered after 08/15/02.*									d nearby	driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No	Date				Badge	e No			Date _			
	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.											
Thi	actions to OPI from School District s bus has been sold, retired, or is no longe	er in serv											
	ase make corrections noted below. Don't County # and County Name	black ou	it the er	ror, OF	PI may ne	eed to read it to make the correction.  District Name							
0						District Marile							
	07 Cascade							at Falls F					
Vehicle I.D. # (VIN) - Entire Number Model Year					ear	Licen	se #		Rated 0	Capacity	, ****		
1GDJ6P1B6KV515596 1989						8506				66			
Chassis Make Body Mak					е		Bus Type	: (see ? f	or defini				
							$\Box$ A [	_ B [	<b>✓</b> C	$\Box$ D			
\A/I	GMC	1 \\/ \	al Ohair	1:4			penter		ַ ט ַ				
	el Chair Lift Equipped?	vvne	ei Chair	LIITE	quipped?								
✓ Ye	es 🗌 No	□ F	orwar	d Fad	cing [	✓ Aisl	e Facing $\;\; \square$ N	ot Applica	able				
Type	of Fuel:	Is B	us:	Distri	ct Owned	✓ C	ontractor Owned If co	ontractor ow	ned, con	tractor's	name	is:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION							
					OUT BY	THE HI	GHWAY PATROL						
	This	inspect			<b>✓</b> 1s	t semes	ster 2nd seme	ster					
D	the see l'atend in the Oten dende	Iv.		oved	10	D	Brance Particulation	the Oterale		1/		roved	To
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach					+	
C18	Head lamps					C18	Interior lamps						†
C10	Color					C18	Ceiling - interior						1
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage					<u> </u>	_
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device					<del> </del>	-
C20	Exterior mirrors Battery		-			C12	Buzzer emergency do Emergency door	J0I				┼──	
C4	Generator or alternator					C18	Red amber signals -	rear					+
C11	Service door					C18	Turn signal lamps - re					†	+
C6	Head lamp indicator					C18	Stop lamps					1	
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear					<u> </u>	
C2	Brakes					C4	Exhaust system (no l	eaks)				<u> </u>	
C21	Driver seat belt					C5 C7	Fuel tank Tires (2/32" rear - 4/3	O" front mir	. \			<del>                                     </del>	-
C13	Steering gear Fire extinguisher (5 lbs)					C/	Cleanliness	2 110111 11111	1.)			+	1
C13	First aid kit					C22	Stop arm						+
C13	Body fluids kit					C5	No trailer hitch						1
C11	Defroster						Required by forest r	egulation:				1	1
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
	umber reference, Standards for School Buses in ot apply. ***New buses ordered after 08/15/02.*										driver.		
	est inspection, this bus is:						einspection, this bus						
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No.			Date			
	ture of District Official					Date	<u> </u>						
Jigila	and or pistriot official					Date							



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.											
Thi	actions to OPI from School District: s bus has been sold, retired, or is no longe	r in serv											
	ease make corrections noted below. Don't County # and County Name	black ou	it the er	ror, OF	PI may ne	eed to read it to make the correction.  District Name							
0						District ratile							
	07 Cascade							at Falls F					
Vehicle I.D. # (VIN) - Entire Number				del Ye	ar	Licen	se#		Rated C	Capacity	, ****		
	1GDJ6P1B7GV511079			198	16		8524			71			
Chassis Make Body Mak					ie e		Bus Type	: (see ? f	or defini				
								•		□ D			
GMC  Wheel Chair Lift Equipped? Wheel Chair Lift Equipped?						/ard	□ A	D	<u>v</u> C	⊔ ט			
wnee	el Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped?								
$\square$ Y	es 🗹 No	☐ F	orwar	d Fac	ing [	☐ Aisl	e Facing 🛮 🗹 N	ot Applica	able				
Туре	of Fuel:	Is B	JS:	Distric	ct Owned	<b>✓</b> C	ontractor Owned If co	ontractor ov	vned, con	tractor's	name	is:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						a						
<u> </u>	as 🗆 Diesei 🗀 Otilei						Big Sky Bus	Lines					
					_	CTION							
							GHWAY PATROL						
	Ihis	inspect			<b>✓</b> 1s	t semes	ster 2nd seme	ster			۸		
Page	Items listed in the Standards	Yes	No	roved NA	Corr	Page	Items listed in	the Standa	rde	Yes	No	roved NA	Corr
No.*	for School Buses in Montana	103	110	**	0011	No.*	for School Bus			103	140	**	0011
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front	<u> </u>			-	C9 Aisle C22 Tools - storage							-
C18	Marker lamps - front Windshield					C22 Tools - storage C24 Windows							
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors	1			+	C13	Buzzer emergency de	oor					+
C3	Battery					C12	Emergency door	-					
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20 C6	Interior mirror Speedometer					C19 C17	Strobe light - rear *** Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank	cans					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	า.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster	<u> </u>			-		Required by forest r						-
C6 C20	Heaters Wheelchair forward facing (post 1993)	<del> </del>			+		Shovel (securely fast Axe (securely fastene	,					+
	umber reference, Standards for School Buses in I	Montana i	2002 Ed	ition). *	***Bus driv	l /ers are r	` '	,	tter attache	d nearby	driver.	L	1
	not apply. ***New buses ordered after 08/15/02.*												
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	Inspecting Patrol Officer:					Inspe	cting Patrol Officer:						
Radas	Badge No. Date					Badge	No.			Date			
		Date				_				ם שנו			
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Tighway Fattor as soon as all defects are corrected.													
Instructions to OPI from School District:													
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ase c	delete it fr	om OPI	s records.						
Please make corrections noted below. Don't black out the error, OPI may ne						ed to read it to make the correction.							
OPI County # and County Name					District Name								
or r county in and county realing						2.5							
07 Cascade						Great Falls Public Schls							
Vehicle I.D. # (VIN) - Entire Number Model Year					License # Rated Capacity *****								
400 1004070\/544000				4000			0524		34				
1GDJ6P1B7GV511080				1986			8531		71				
Chassis Make Bod				Body Mal									
GMC				$\square$ A $\square$ B	$\square$ B $\checkmark$ C $\square$ D								
			Wheel Chair Lift Equipped?				ard						
		1 – .		J	-:								
☐ Y			Forward Facing Aisle Facing Vot Applicable										
Туре	of Fuel:	Is B	Is Bus: ☐ District Owned ✔ Contractor Owned If contractor owned, contractor's name is:										
<b>✓</b> G	as $\square$ Diesel $\square$ Other		Dim Olay Prog. Library										
							Big Sky Bus	Lines					
						CTION							
							GHWAY PATROL						
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ter 2nd semes	ster					
			Appro	oved						App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t		Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Buse				**		
C17	Identification - front					C34	Belt cutter **** attache	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	ÿ						
C18	Windshield					C24							
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors	<u> </u>			_	C13	ů ,				<u> </u>	<u> </u>	
C3	Battery					C12 C18	Ů ,						
C4 C11	Generator or alternator Service door					C18	ŭ			-			
C6	Head lamp indicator					C18	Ŭ İ				1	-	
C6	Horn	1			-	C18	Stop lamps		-	1	1		
C20	Interior mirror					C19	· · · · · · · · · · · · · · · · · · ·						
C6	Speedometer					C17							
C2	Brakes					C4							
C21	Driver seat belt		<del>                                     </del>		+	C5	Fuel tank	20.10/	+	1	†	1	
C7	Steering gear					C7				1	1	1	
C13	Fire extinguisher (5 lbs)					<u> </u>	Cleanliness	,		†	†		
C13	First aid kit					C22	Stop arm			†	†		
C13	Body fluids kit					C5	No trailer hitch			†	†		
C11	Defroster						Required by forest re	egulation:		1	1	1	
C6	Heaters				1		Shovel (securely fastened)					1	
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)							
*Page n	umber reference, Standards for School Buses in I	Montana (	(2002 Edit	ion).	****Bus dri	vers are r	equired to wear lap/should	ler belts - cutter attach	ed nearby	driver.	•	•	
**Does	not apply. ***New buses ordered after 08/15/02.**	***Basec	l on origina	al cap	acity listed	on the m	anufacturers certification to	ag found inside the bu	s				
On fi	rst inspection, this bus is:					On re	inspection, this bus	is:					
Approved						Approved							
□ Not Approved						□ Not Approved							
Inspecting Patrol Officer:				Inspecting Patrol Officer:									
Badge No Date					Badge No Date								
Signature of District Official				Date									



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Hignw	ay Patrol as soon as all defects are correcte	ea.											
	uctions to OPI from School District:	in sarv	ica Plaa	22	delete it fr	nm OPI	's records						
This bus has been sold, retired, or is no longer in service. Please delete it from OF Please make corrections noted below. Don't black out the error, OPI may need to								action					
	County # and County Name	nack ou	t tile ello	i, C	71 Tillay III	District Name							
	07 Cascade						Gre	at Falls I	Public S	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Mode	el Y	'ear	Licen			Rated C		****		
	1GDJ6P1B7HV526759			10	87		8504			, ,	15		
Chas	sis Make			<del>    3</del>	Body Mal	<u> </u>	0304	Bus Type	e: (see ? fo	or defini			
Ondo					Dody Mai			□ A	`	✓ C	, □ D		
Whee	GMC el Chair Lift Equipped?	Whe	el Chair L	ift I	Equipped?		ayne						
✓ Y			orward				e Facing	ot Applic	ahle				
	of Fuel:						ontractor Owned If co			tractor's	name	ie.	
		13 00	is L	JiSti	ict Ownec	V	ontractor Owned in co	nitiacioi ov	vilea, com	ilacioi s	Hairie	ъ.	
□G	as   Diesel  Other						Big Sky Bus	Lines					
		т.	DE EU 1		_	CTION	OLIMAN BATBOL						
	This	_	on is for:	.ED		t semes	GHWAY PATROL ster	etor					
	11115	irispecii	Approv	ved		i semes	stei Zhu seines	Siei			Ann	roved	
Page	Items listed in the Standards	Yes		VOG NA	Corr	Page	Items listed in	the Standa	rds	Yes	No	NA	Corr
No.*	for School Buses in Montana		*	*		No.*	for School Bus					**	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps					<u> </u>	
C10	Color					C18	Ceiling - interior					<u> </u>	+
C18	Turn signal lamps - front					C21	Seating					<b>├</b> ──	+
C18	Turn signal lamps - side (post 1987) Red amber signals - front					C14 C9	Floor Aisle					+	+
C18	Marker lamps - front					C22	Tools - storage					+	+
C18	Windshield					C24	Windows					1	+
C24	Windshield wipers					C13	Warning device					†	†
C20	Exterior mirrors					C13	Buzzer emergency do	or				1	
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear				<b>↓</b>	
C6	Head lamp indicator					C18	Stop lamps					<u> </u>	_
C6 C20	Horn Interior mirror					C18 C19	Marker lamps - rear Strobe light - rear ***						_
C6	Speedometer					C17	Identification - rear					+	+
C2	Brakes					C4	Exhaust system (no l	eaks)				1	+
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mi	n.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm					<u> </u>	
C13	Body fluids kit					C5	No trailer hitch					<del> </del>	
C11 C6	Defroster Heaters						Required by forest r Shovel (securely faste					+	+
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene					+	+
*Page n	umber reference, Standards for School Buses in M						required to wear lap/should	der belts - cu			driver.		
"Does i	not apply. ***New buses ordered after 08/15/02.***	Based	on original	cap	Dacity listed	on the m	anuracturers certification t	ag round ins	iue the bus.				
On fi	rst inspection, this bus is:			_		On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:						cting Patrol Officer:						
Badge		Date					e No			Date			
Signa	ture of District Official					Date							
											TR-1	3 Revise	ed 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

riigiiw	ay Fatiol as soon as all defects are correct	.cu.											
Instru	ections to OPI from School District:												
	s bus has been sold, retired, or is no longe												
☐ Ple	ase make corrections noted below. Don't	black ou	it the err	or, O	PI may ne	eed to re	ead it to make the corre	ection.					
OPI County # and County Name					Distri	ct Name							
	07 Casada						0	-4 Falla F	)hl:a C	<b>Sabla</b>			
Vahia	07 Cascade		Mar	del Y	`aar	Licen		at Falls F	Rated C		****		
venic	le I.D. # (VIN) - Entire Number		IVIO	Jei i	ear	Licen	se #		Raied C	араспу			
	1GDJ6P1B7JV526072			19	88		8513				66		
Chas	sis Make		•		Body Mal	се		Bus Type	: (see ? fo	or defini	tion)		
	0110					_		$\Box$ A	□в [	<b>✓</b> C	$\Box$ D		
Mhac	GMC el Chair Lift Equipped?	Who	al Chair	1 :£4 F	Equipped?		penter		ַ ט				
vvnee													
☐ Ye	es 🗹 No	□ F	orward	d Fa	cing	AisI	e Facing 🛮 🗹 No	ot Applica	able				
Туре	of Fuel:	Is B	us:	Distr	ict Owned	I ✔ C	ontractor Owned If co	ntractor ow	ned, cont	tractor's	name	is:	
<b>✓</b> G	as □ Diesel □ Other												
<b>▼</b> G	as 🗆 Diesei 🗀 Ottlei						Big Sky Bus	Lines					
						CTION							
							GHWAY PATROL						
	This	inspect	ion is for			t semes	ster 2nd semes	ster					
			Appro				1			1	. ''	roved	
Page	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page	Items listed in t			Yes	No	NA **	Corr
No.*						No.*	for School Buse Belt cutter **** attache		ına			_	-
C17	Identification - front Head lamps	1			_	C18	Interior lamps	<del>e</del> u				+	+
C10	Color					C18	Ceiling - interior					+	+
C18	Turn signal lamps - front					C21	Seating					+	1
C18	Turn signal lamps - side (post 1987)					C14	Floor					1	
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows					1	
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	or					
C3	Battery					C12	Emergency door					<u> </u>	
C4	Generator or alternator					C18	Red amber signals -					<b>↓</b>	
C11	Service door	<u> </u>			_	C18	Turn signal lamps - re	ar				<b>├</b>	<del> </del>
C6 C6	Head lamp indicator  Horn				-	C18	Stop lamps Marker lamps - rear					+-	+
C20	Interior mirror					C19	Strobe light - rear ***					+	+
C6	Speedometer					C17	Identification - rear					+	+
C2	Brakes	1				C4	Exhaust system (no le	eaks)				+	+
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min	า.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch					<u> </u>	
C11	Defroster						Required by forest r	_				<b>↓</b>	
C6	Heaters						Shovel (securely fasters	,				_	-
C20	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in I	Montana	(2002 Edit	ion)	****Buc dri	(ore are r	Axe (securely fastene	,	tor attacho	d poarby	drivor		
	not apply. ***New buses ordered after 08/15/02.**										unver.		
	rst inspection, this bus is:						einspection, this bus	is:					
	Approved Not Approved						Approved Not Approved						
	••						• •						
mspec	cting Patrol Officer:					mspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No			Date			
Signa	ture of District Official					Date							
•													



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	Highway Patrol as soon as all defects are corrected.												
Instru	ictions to OPI from School District:	i i											
☐ Thi	s bus has been sold, retired, or is no longe	r in serv	vice. Pl	ease de	elete it fi	om OPI	's records.						
☐ Ple	ase make corrections noted below. Don't	black o	ut the e	rror, OF	PI may n	eed to re	ead it to make the corr	ection.					
OPI County # and County Name				Distri	ct Name								
07 Cascade					Gre	at Falls F	Public S	Schls					
Vehic	le I.D. # (VIN) - Entire Number		M	odel Ye	ar	Licen				Capacity	/ ****		
	1GDJ6P1B7KV514831			198	0		8463				66		
Chas	sis Make				Body Ma	ke.	0403	Bus Type	: (see ? f	or defin			
Onao					ouy ma				,	✓ C	□ D		
Who	GMC el Chair Lift Equipped?	\//bc	ol Chai	r l ift ⊑	quipped'		penter		<b>D</b>				
☐ Ye		<u> </u>	orwa					ot Applica					
Type	of Fuel:	Is B	us:	Distric	ct Owner	d 🔽 C	ontractor Owned If co	ontractor ow	ned, con	tractor's	name	is:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION							
		TO	BE FI	LLED (			GHWAY PATROL						
	This	inspect	tion is fo	or:	<b>✓</b> 19	st semes	ster 2nd seme	ster					
			Арр	roved							App	roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach		ша	<del>                                     </del>		+-	
C18	Head lamps					C18	Interior lamps	icu .				+-	
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating					1	
C18	Turn signal lamps - side (post 1987)					C14	Floor			1		1	
C18	Red amber signals - front					C9	Aisle					1	
C18	Marker lamps - front					C22	Tools - storage					1	
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency d	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - r	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front mir	ı.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest	regulation:					
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
	umber reference, Standards for School Buses in I										driver.		
	**Does not apply. ***New buses ordered after 08/15/02.*****Based on original capacity listed on the manufacturers certification tag found inside the bus.												
	rst inspection, this bus is: Approved						einspection, this bus Approved	IS:					
	Approved						Approved						

On reinspection, this bus is:
Approved
Not Approved
Inspecting Patrol Officer:
e Date
Date
Not Approved Inspecting Patrol Officer:  Badge No Date



C13

C11

C6

Body fluids kit

Wheelchair forward facing (post 1993)

Defroster

Heaters

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1B7KV514850 1989 8511 66 Bus Type: (see ? for definition) Chassis Make Body Make ПА ПВ ✓ C  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Type of Fuel: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No NA Items listed in the Standards Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating C18 Turn signal lamps - side (post 1987) C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	

C5

No trailer hitch

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)



### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1BXFV509385 1985 8525 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Ward **GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ☐ Gas Diesel Other Big Sky Bus Lines INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch Defroster C11 Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correct	ed.											
	actions to OPI from School District: s bus has been sold, retired, or is no longe		vice. Ple	ase o	delete it fr	om OPI	's records.						
$\hfill \square$ Please make corrections noted below. Don't black out the error, OPI may n						eed to re	ead it to make the corr	ection.					
OPI County # and County Name						District Name							
	07 Cascade					Great Falls Public Schls							
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen			Rated C		****		
	40D ICD4DVI/VE44700			40	00		0500				cc		
Chac	1GDJ6P1BXKV514760 sis Make			19	Body Mal	(O	8508	Bus Type	· (saa 2 fe	or defini	66		
Cilas	ois iviane				bouy iviai	ve.		• •	•		,		
	GMC						penter	□ A [	□В	<b>✓</b> C			
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?	•							
✓ Y	es 🗆 No	│□F	orward	d Fa	cina	✓ Aisl	e Facing  \Quad N	ot Applica	able				
	of Fuel:						ontractor Owned If co			tractor's	name i	s.	
• •		10 5	uo	D10111		. 👿 🔾	ontractor owned in oc	milacioi on	1100, 0011	aotor o	namo i	0.	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION				,			
					OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd semes	ster					
			Appro				,					roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach		ша	<u> </u>	<u> </u>	┼	+
C17	Head lamps	1				C18	Interior lamps	eu		├──	$\vdash$	$\vdash$	+
C10	Color	1				C18	Ceiling - interior			<del>                                     </del>	<del>                                     </del>		+
C18	Turn signal lamps - front					C21	Seating					<b>†</b>	
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device					<u> </u>	
C20	Exterior mirrors					C13	Buzzer emergency do	oor		<u> </u>	<u> </u>	<b>↓</b>	
C3	Battery					C12	Emergency door			<u> </u>	<u> </u>	<del>                                     </del>	
C4 C11	Generator or alternator					C18	Red amber signals -						
Cfi	Service door Head lamp indicator	1				C18	Turn signal lamps - re Stop lamps	al		├──	├──	┼─	+
C6	Horn					C18	Marker lamps - rear				1	<del>                                     </del>	+
C20	Interior mirror					C19	Strobe light - rear ***					<del>                                     </del>	+
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	n.)			<b>└</b>	
C13	Fire extinguisher (5 lbs)						Cleanliness			<u> </u>	<u> </u>	<b>↓</b>	<u> </u>
C13	First aid kit					C22	Stop arm			<u> </u>	<u> </u>	<del>                                     </del>	
C13	Body fluids kit  Defroster					C5	No trailer hitch	agulation		<u> </u>	<u> </u>	<del>                                     </del>	-
C6	Heaters						Required by forest r Shovel (securely faste					<del>                                     </del>	+
C20	Wheelchair forward facing (post 1993)	1					Axe (securely fastene			<del>                                     </del>	<del>                                     </del>		+
*Page n	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**						equired to wear lap/should	der belts - cut			driver.		
		24500	. J Origini	oap	, noted								
On fi	st inspection, this bus is:						einspection, this bus	is:					
닏	Approved						Approved						
	Not Approved					_	Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No	Date				Badge No Date							
Signa	ture of District Official					Date							



C13

C11

C6

C20

Body fluids kit

Wheelchair forward facing (post 1993)

Defroster

Heaters

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDJ6P1P4MV500495 1991 8539 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Ward **GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Type of Fuel: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C18 C6 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:				
Approved		Approved				
Not Approved		Not Approved				
Inspecting Patrol Officer:		Inspecting Patrol Officer:				
			_			
Badge No.	Date	Badge No.	Date			
Signature of District Official		Date				

C5

No trailer hitch

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)



Brakes

C13

C13

C11

C6

C20

Driver seat belt

Fire extinguisher (5 lbs)

Wheelchair forward facing (post 1993)

Steering gear

Body fluids kit

First aid kit

Defroster

Heaters

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena, MT 59620-2501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDL1T1PTR1517031 1994 **B741** Bus Type: (see ? for definition) Chassis Make Body Make ПА □в ✓ C  $\Box$  D **GMC Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On macinapection, this bus is.		On remspection, this bus is.					
Approved		Approved					
Not Approved		Not Approved					
Inspecting Patrol Officer:		Inspecting Patrol Officer:					
Badge No.	Date	Badge No.	Date				
Signature of District Official		Date					

C4

C22

C5

Exhaust system (no leaks)

Tires (2/32" rear - 4/32" front min.)

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)

Fuel tank

Cleanliness

Stop arm
No trailer hitch

\_ ----



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

riigiiw	ay Fallol as soon as all delects are correct	.cu.											
	ections to OPI from School District:												
	s bus has been sold, retired, or is no longe												
Please make corrections noted below. Don't black out the error, OPI may nee													
OPI (	County # and County Name					Distri	ct Name						
07 Cascade						Great Falls Public Schls							
Vehic	le I.D. # (VIN) - Entire Number		Mod	lel Y	'ear	Licen		at i alis i	Rated C		****		
	, ,									,			
	1GDL6P1P2LV512894			19	90		8538		, ,,		71		
Chas	sis Make				Body Mal	ке		Bus Type	: (see ? to	or defini	tion)		
	GMC					Blu	ebird	$\Box$ A	⊒в [	<b>✓</b> C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift [	Equipped?								
□ Y	es 🗹 No		orward	l Fa	cina	Δisl	e Facing 🗹 N	ot Applica	ahle				
	of Fuel:	Is B					ontractor Owned If co			tractor's	nama	ic:	
		19 01	us	Disti	ici Ownec	<b>V</b> C	ontractor Owned in co	illiacioi ow	neu, com	liacioi s	Hallie	15.	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INSPE	CTION							
		TC	BE FIL	LED	OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is for		<b>✓</b> 1s	t semes	ster 2nd semes	ster					
			Appro								. ''	roved	_
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in t for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attache		IIIa			+	-
C17	Head lamps					C18	Interior lamps	eu				1	-
C10	Color	1				C18	Ceiling - interior					1	1
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor					1	
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows					<b>↓</b>	<u> </u>
C24	Windshield wipers					C13	Warning device					<b>↓</b>	
C20	Exterior mirrors  Battery					C13	Buzzer emergency do Emergency door	oor				<del> </del>	-
C4	Generator or alternator					C12	Red amber signals -	rear				+	+
C11	Service door					C18	Turn signal lamps - re					†	1
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear					1	
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear					<u> </u>	
C2	Brakes					C4	Exhaust system (no le	eaks)				<u> </u>	<u> </u>
C21 C7	Driver seat belt Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	O" front min				<del> </del>	-
C13	Fire extinguisher (5 lbs)					C/	Cleanliness	2 110111 11111	1.)			+	+
C13	First aid kit					C22	Stop arm						+
C13	Body fluids kit	1				C5	No trailer hitch					1	1
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely faste	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**										driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No.			Date			
	ture of District Official					Date				_			
J -													



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDL6P1P7LV512891 1990 8537 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date

Date

Date

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	.,												
Instructions to OPI from School District:													
This bus has been sold, retired, or is no longer in service. Please delete it fr						om OPI	s records.						
Please make corrections noted below. Don't black out the error, OPI may need						eed to read it to make the correction.							
OPI County # and County Name					District Name								
	,												
	07 Cascade						Grea	at Falls Public					
Vehic	cle I.D. # (VIN) - Entire Number		Мо	del Y	ear	Licen	se#	Rated	Capacity	/ ****			
	4 CDL CC4 DOEVC4 424 0			40	0.E		0522			<b>CO</b>			
01	1GDL6S1B0FV614318				85 Barba Mad		8532	Due Times (see 2	for dofin	69			
Chas	sis Make				Body Mak	æ		Bus Type: (see ?		itiori)			
	GMC					W	ard	$\square$ A $\square$ B	✓ C	$\Box$ D			
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	Equipped?		<u></u>						
							- · -						
☐ Y								ot Applicable					
Туре	of Fuel:	Is Bu	us:	Distr	ict Owned	✓ C	ontractor Owned If co	ntractor owned, co	ntractor's	name	is:		
□G	as □ Diesel ☑ Other						D' Ol D						
							Big Sky Bus	Lines					
					INSPE	CTION							
		TC	BE FIL	.LED			GHWAY PATROL						
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ter 2nd semes	ster					
			Appr	oved						App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t		Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus				**		
C17	Identification - front					C34	Belt cutter **** attache	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21 Seating							
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield			C24 Windows									
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery	<u> </u>			_	C12	Emergency door			<u> </u>	<u> </u>	-	
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C20	Speedometer	1			_	C17	Identification - rear			1	1		
C2	Brakes					C4	Exhaust system (no le	aake)					
C21	Driver seat belt					C5	Fuel tank	cars)					
C7	Steering gear	<del> </del>				C7	Tires (2/32" rear - 4/3	2" front min )		<del>                                     </del>	<del>                                     </del>	1	
C13	Fire extinguisher (5 lbs)	<del> </del>				, , , , , , , , , , , , , , , , , , ,	Cleanliness			<del>                                     </del>	<del>                                     </del>	1	
C13	First aid kit	1				C22	Stop arm					1	
C13	Body fluids kit	1				C5	No trailer hitch					1	
C11	Defroster						Required by forest r	egulation:		1	<del>                                     </del>	1	
C6	Heaters	i i					Shovel (securely faste	_				1	
C20	Wheelchair forward facing (post 1993)	i i					Axe (securely fastene					1	
	umber reference, Standards for School Buses in I	Montana (	2002 Edi	tion).	****Bus driv	ers are r	` '	,	ned nearby	driver.			
	not apply. ***New buses ordered after 08/15/02.**												
On fi	rst inspection, this bus is:					On re	inspection, this bus	ie·					
	Approved						Approved						
片	Not Approved						Not Approved						
	• •												
ınspe	cting Patrol Officer:					inspe	cting Patrol Officer:						
Badge	e No.	Date				Badge	No.		Date				
	ture of District Official	-	-		-	Date	<del></del>		_				
Jigila	and the second s					Date							



### **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correc	ted.											
	actions to OPI from School District												
_	s bus has been sold, retired, or is no longe ase make corrections noted below. Don't							ection					
OPI County # and County Name						·							
OFI County # and County Name					District Name								
	07 Cascade						Gre	at Falls F					
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen	se #		Rated	Capacity	/ ****		
	1GDL7T109TJ501436			199	6		8542		i		72		
Chas	sis Make		L		ody Mał	ke	00+ <u>L</u>	Bus Type	: (see ?	for defin			
					,				_ □ B	<b>✓</b> C	D		
100	Other	1 147	101 :	1:6: 5			<u>iebird</u>	□A	<u> b</u>	<u>• C</u>	<u>u</u>		
vvnee	el Chair Lift Equipped?	vvne	ei Chair	LITTEC	uipped?								
☐ Y	es 🗹 No	□ F	orwar	d Fac	ing [	_ Aisl	e Facing 🗹 N	ot Applica	able				
Туре	of Fuel:	Is Bu	JS:	Distric	t Owned	l <b>√</b> C	ontractor Owned If co	ontractor ow	ned, co	ntractor's	name	is:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						D' Ol D						
							Big Sky Bus	Lines					
						CTION							
					_		GHWAY PATROL						
	Ihis	inspect			<b>✓</b> 1s	t semes	ster 2nd seme	ster			۸		
Page	Items listed in the Standards	Yes	Appr No	oved NA	Corr	Page	Items listed in	the Standay	rde	Yes	App No	noved NA	Corr
No.*	for School Buses in Montana	165	INO	**	Con	No.*	for School Bus			165	INO	**	Con
C17	Identification - front					C34	Belt cutter **** attach	ned		+		1	†
C18	Head lamps					C18	Interior lamps				1		
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle				<b>└</b>	<b>↓</b>	
C18	Marker lamps - front					C22	Tools - storage			_	<b>↓</b>	<b>↓</b>	
C18	Windshield				1	C24	Windows				₩	<b>↓</b>	+
C24	Windshield wipers					C13	Warning device					+	+
C20	Exterior mirrors Battery	-			1	C13 C12	Buzzer emergency d Emergency door	001			┼──	+	+
C4	Generator or alternator					C12	Red amber signals -	rear		-	+	+	+
C11	Service door					C18	Turn signal lamps - r			-	+	+	+
C6	Head lamp indicator	1			1	C18	Stop lamps			-	†	+	†
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no	eaks)					
C21	Driver seat belt					C5	Fuel tank			_	<b>↓</b>	<b>↓</b>	
C7	Steering gear				-	C7	Tires (2/32" rear - 4/3	32" front mir	1.)	+	<del> </del>	<b>∔</b> —	+
C13	Fire extinguisher (5 lbs)					COO	Cleanliness					+	+
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch				┼──	+	+
C11	Defroster Defroster					03	Required by forest	regulation:		+-	┼──	+	+
C6	Heaters	+			†		Shovel (securely fast	_		+	+	†	+
C20	Wheelchair forward facing (post 1993)				<u> </u>		Axe (securely fastene	,		+	<del>                                     </del>	†	+
*Page n	umber reference, Standards for School Buses in						required to wear lap/shoul	der belts - cut			driver.	1	
**Does	not apply. ***New buses ordered after 08/15/02.*	****Based	l on origir	nal capa	city listed	on the m	anufacturers certification	tag found insi	de the bu	is.			
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspecting Patrol Officer:						Inspe	cting Patrol Officer:						

Badge No. Date Signature of District Official Date



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDL7T1P5SJ521732 1996 3065 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No. Date

Signature of District Official



Date

Signature of District Official

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDL7T1P5TJ501787 1996 8526 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Tilgitwo	ay Patrol as soon as all defects are correcte	u.											
Instru	ctions to OPI from School District:												
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
Ple	ase make corrections noted below. Don't b	lack ou	it the erro	or, C	OPI may ne	eed to read it to make the correction.							
OPI C	County # and County Name					District Name							
	, , , , , , , , , , , , , , , , , , , ,												
	07 Cascade						Gre	at Falls P					
Vehic	le I.D. # (VIN) - Entire Number		Mod	lel Y	⁄ear	Licen	se#		Rated C	Capacity	****		
	1GDL7T1P6TJ515309			40	97		D489				71		
Chas	sis Make			+	Body Mak		D409	Bus Type:	(soo 2 fe	or defini			
Cilas	ois ware				bouy war	ve.			•				
	GMC					Blu	ebird	$\Box$ A $\Box$	В	✓ C	$\Box$ D		
Whee	Chair Lift Equipped?	Whe	el Chair	Lift	Equipped?								
☐ Ye	es 🗹 No	l⊓⊧	orward	ΙFα	ecina [	Δiel	e Facing <b>☑</b> N	ot Applica	hla				
туре	of Fuel:	Is Bu	ıs:	Dist	rict Owned	<b>✓</b> C	ontractor Owned If co	ontractor owi	ned, con	tractor's	name	S:	
<b>✓</b> G:	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
					INIODE	OTION	Big Oky Buc						
		тс	DE EII	. =	INSPE		GHWAY PATROL						
	This i		ion is for			t semes		otor					
	Triis i	nspeci				csemes	ster znd semes	ster			۸nn	round	
Page	Items listed in the Standards	Yes	Appro No	NA	Corr	Page	Items listed in	the Standar	do	Yes	No No	noved NA	Corr
No.*	for School Buses in Montana	165	INO	**	Con	No.*	for School Bus			168	INO	**	Con
C17	Identification - front					C34	Belt cutter **** attach						
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps					<b>.</b>	-
C6	Horn Interior mirror					C18 C19	Marker lamps - rear Strobe light - rear ***						
C20 C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	oake)					
C21	Driver seat belt					C5	Fuel tank	cans)					
C7	Steering gear		1			C7	Tires (2/32" rear - 4/3	2" front min	.)				1
	Fire extinguisher (5 lbs)						Cleanliness		,	1	<del>                                     </del>		1
C13	First aid kit					C22	Stop arm				i e		1
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	egulation:					<u> </u>
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
	umber reference, Standards for School Buses in M not apply. ***New buses ordered after 08/15/02.***										driver.		
On fi	st inspection, this bus is:					On re	einspection, this bus	ie.					
	•						Approved	10.					
☐ Approved ☐ Not Approved						Not Approved							
					• •								
ınspec	ting Patrol Officer:					Inspecting Patrol Officer:							
Badge		Date				Badge No Date							
Signat	rure of District Official					Date							
											TR-1	3 Revise	ed 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highway Patrol as soon as all defects are corrected.													
Instru	ctions to OPI from School District												
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
☐ Please make corrections noted below. Don't black out the error, OPI may ne							eed to read it to make the correction.						
OPI County # and County Name						District Name							
							_						
	07 Cascade		1					at Falls F					
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ear	Licen	se#		Rated C	Capacity	****		
	1GDL7T1P7SJ522056			199	96		3067				71		
Chas	sis Make				Body Mal	е		Bus Type	: (see ? fo	or defini			
					,			□ A [	□B VC □D				
	GMC	1					ebird	□A	<b>D</b> [	<u>v</u> C	∐ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?	'							
□ Ye	es 🗹 No		orwar	d Fa	cing [	☐ Aisl	e Facing 🔽 N	ot Applica	able				
Type	of Fuel:	Is B	us:	Distri	ct Owned	✓ C	ontractor Owned If co	ontractor ow	ned. cont	tractor's	name i	s:	
									•				
<b>✓</b> G	as 🗌 Diesel 🗌 Other						Big Sky Bus	Lines					
					INSPE	CTION							
		TC	BE FIL	LED	OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ster 2nd semes	ster					
			Appr	oved							Appı	roved	
Page	Items listed in the Standards	Yes	No	NA **	Corr	Page	Items listed in			Yes	No	NA **	Corr
No.*	for School Buses in Montana					No.*	for School Bus		ına		<u> </u>		
C17	Identification - front					C34 C18	Belt cutter **** attach	ea					
C18 C10	Head lamps Color	1				C18	Interior lamps Ceiling - interior				├──	$\vdash$	
C18	Turn signal lamps - front					C21	Seating				<del>                                     </del>	<del>                                     </del>	
C18	Turn signal lamps - side (post 1987)					C14	Floor					1	
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front	1				C22 Tools - storage			<del>                                     </del>				
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -				<u> </u>	<u> </u>	
C11	Service door					C18	Turn signal lamps - re	ear			<u> </u>	<u> </u>	
C6 C6	Head lamp indicator Horn					C18 C18	Stop lamps Marker lamps - rear						
C20	Interior mirror	1			-	C19	Strobe light - rear ***				<del> </del>	<del> </del>	
C6	Speedometer	+			+	C17	Identification - rear				1	1	
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt	1				C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	n.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r						
C6	Heaters	<u> </u>					Shovel (securely fast				<del>                                     </del>	<del>                                     </del>	ļ
C20	Wheelchair forward facing (post 1993)	4	(0000 F-I	·\ 1	*****		Axe (securely fastene	,	4	-ll		<u></u>	
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**										uriver.		
			. 5	- 1-	,								
	st inspection, this bus is:						einspection, this bus	is:					
	Approved						Approved Not Approved						
Not Approved						• •							
inspec	eting Patrol Officer:					inspe	cting Patrol Officer:						
Badge	No	Date				Badge	e No.			Date			
	ure of District Official					Date							
-						1							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GDL7T1P8TJ501489 1996 8520 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird** Other Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDL7T1PXSJ521838 1996 3066 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVBBPLM7PH527291 1993 6130 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ☐ Forward Facing ✓ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Instructions to OPI from School District:													
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
	ase make corrections noted below. Don't	black ou	t the err	or, C	OPI may ne	eed to read it to make the correction.							
OPI (	County # and County Name					Distri	ct Name						
	07 Cascade						Gre	at Falls F	Public S	Schle			
Vehic	le I.D. # (VIN) - Entire Number		Mod	del \	/ear	Licen		at i alis i	Rated C		/ ****		
	, ,												
	1HVBBPLM9PH527292			19	993		6125	D T	/ 0.1		35		
Chas	sis Make				Body Mak	æ			e: (see ? f		•		
	International					An	ntran	$\square$ A	□ B	✓ C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift	Equipped?								
□ Ye	es 🗹 No		orward	1 [	acina [	\ \ick	e Facing 🔽 N	ot Applica	ahla				
туре	of Fuel:	IS BU	ıs:	DIST	rict Owned	<b>✓</b> C	ontractor Owned If co	ontractor ov	vnea, con	tractors	name	IS:	
$\Box$ G	as 🗹 Diesel 🗌 Other						Big Sky Bus	Lines					
		•			INSPE	CTION							
		TC	BE FIL	LEC			GHWAY PATROL						
	This	inspecti	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd semes	ster					
		•	Appro	ovec							App	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in			Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		ana			**	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps					1	+
C10	Color Turn signal lamps front					C18 C21	Ceiling - interior						-
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)	1				C14	Seating Floor					<u> </u>	+
C18	Red amber signals - front					C9	Aisle						-
C18	Marker lamps - front					C22 Tools - storage				1			
C18	Windshield					C24 Windows					+		
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13	Buzzer emergency do	or					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18 Turn signal lamps - rear							
C6	Head lamp indicator	<u> </u>				C18	Stop lamps Marker lamps - rear			1		-	<del> </del>
C6 C20	Horn Interior mirror					C18 C19	Strobe light - rear ***						+
C6	Speedometer					C17	Identification - rear						+
C2	Brakes					C4	Exhaust system (no le	eaks)					+
C21	Driver seat belt					C5	Fuel tank	,				t	1
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	า.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm					1	<b>_</b>
C13	Body fluids kit					C5	No trailer hitch			1		1	<del> </del>
C11 C6	Defroster Heaters						Required by forest r					+	+
C20	Wheelchair forward facing (post 1993)						Shovel (securely faste Axe (securely fastene	,				1	+
	umber reference, Standards for School Buses in I	Montana (	2002 Edit	ion)	****Bus driv	ers are r	. (	-,	tter attache	d nearby	driver.	1	
	not apply. ***New buses ordered after 08/15/02.**												
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
☐ Not Approved					Not Approved								
Inspe	cting Patrol Officer:					Inspec	cting Patrol Officer:						
-													
Badge		Date				Badge	e No			Date _			
Signa	ture of District Official					Date							



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVBBPLP1PH527328 1993 6129 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved

Not Approved

Not Approved

Inspecting Patrol Officer:

Badge No.

Date

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVBBPLP4PH527324 1993 7446 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	actions to OPI from School Districts s bus has been sold, retired, or is no longer		rice. Ple	ase	delete it fr	om OPI	s records.						
	ase make corrections noted below. Don't	black ou	it the err	or, C	PI may ne			ection.					
OPI (	County # and County Name					Distri	ct Name						
	07 Cascade						Gre	at Falls I					
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	'ear	Licen	se#		Rated C	apacity	****		
	1HVBBPLP6PH527308			19	93		6128				77		
Chas	sis Make			_	Body Mak	е		Bus Type	e: (see ? fo	or defini			
	International					۸n	ntran	$\square$ A	□в •	✓ C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift I	Equipped?		iliaii						
□ Ye			orward				e Facing 🗹 N	ot Applic	ahla				
	of Fuel:						ontractor Owned If co			rootor'o	nomo	io:	
		15 00	JS	DIST	ict Owned	V C	ontractor Owned in co	miliacioi ov	viiea, cont	iacioi s	паше	15.	
□G	as 🗹 Diesel 🗌 Other						Big Sky Bus	Lines					
					_	CTION							
							GHWAY PATROL						
	Ihis	inspect	ion is for Appro			t semes	ter 2nd semes	ster			۸nn	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standa	rds	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus	es in Monta	ana			**	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps					<u> </u>	
C10	Color					C18	Ceiling - interior					<u> </u>	
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)					C21 C14	Seating Floor						
C18	Red amber signals - front					C14	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	or					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear					1	
C20 C6	Interior mirror Speedometer					C19 C17	Strobe light - rear *** Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt				+	C5	Fuel tank	cans					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mii	า.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r						
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in I	Aontana (	2002 Edit	ion)	****Buc driv	ore are r	Axe (securely fastene		ttor attachor	d noarby	drivor		
	not apply. ***New buses ordered after 08/15/02.**									и пеагру	unver.		
On fi	rst inspection, this bus is:					On re	inspection, this bus	is:					
	Approved						Approved	13.					
Not Approved				Not Approved									
Inspecting Patrol Officer:				cting Patrol Officer:									
Badge		Date				Badge				Date			
Signa	ture of District Official					Date							_



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

	ay Patrol as soon as all defects are correct		11 20-10	, 101, I	non. Ai	i vernore	s not approved on ms	t inspection mus	st be remape	cted by	li iC	
Instru	ctions to OPI from School District:											
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
Ple	ase make corrections noted below. Don't	black ou	it the er	ror, OF	l may n	eed to re	ead it to make the corr	ection.				
OPI C	County # and County Name					Distri	ct Name					
	07 Cascado						Gro	at Falle Bub	lic Schle			
Vehic	le I.D. # (VIN) - Entire Number		Mc	del Ye	ar	Licen		at Falls Pub	ated Capacity	/ ****		
V 01110	, ,		'''			Lioon		1	atou Oupuoit,			
	1HVBBPLP6PH527339			199	•		6131	Don't Time (a)	O ( d - f' -	<u>77</u>		
Chas	sis Make				Body Mal	ke		Bus Type: (se	ee? for defin	ition)		
	International					An	ntran	□ A □ E	3 <b>▼</b> C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chai	r Lift Ed	quipped?			•				
☐ Ye	es 🗹 No		orwar	d Fac	ina	Aisl	e Facing <b>☑</b> N	ot Applicable	<b>5</b>			
	of Fuel:	Is Bu					ontractor Owned If co			name i	s.	
		10 5		Diotire	. •				i, contractor c	riamo	0.	
□G	as 🗹 Diesel 🗌 Other						Big Sky Bus	Lines				
					_	CTION						
							GHWAY PATROL					
	This	inspect			<b>✓</b> 1s	t semes	ster 2nd seme	ster		۸		
Page	Items listed in the Standards	Yes	No	noved NA	Corr	Page	Items listed in	the Standards	Yes	No App	roved NA	Corr
No.*	for School Buses in Montana	163	INO	**	Con	No.*	for School Bus		163	INO	**	Con
C17	Identification - front					C34	Belt cutter **** attach	ned				
C18	Head lamps					C18	Interior lamps					
C10	Color					C18	Ceiling - interior					
C18	Turn signal lamps - front					C21	Seating					
C18	Turn signal lamps - side (post 1987) Red amber signals - front					C14 C9	Floor Aisle					
C18	Marker lamps - front					C22	Tools - storage			1		
C18	Windshield					C24	Windows					
C24	Windshield wipers					C13	Warning device					
C20	Exterior mirrors					C13	Buzzer emergency d	oor		1		
C3	Battery					C12	Emergency door					
C4	Generator or alternator					C18	Red amber signals -					
C11	Service door					C18	Turn signal lamps - r	ear				
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear			1		
C20	Interior mirror				+	C19	Strobe light - rear ***			<del> </del>		
C6	Speedometer				1	C17	Identification - rear			1		
C2	Brakes				1	C4	Exhaust system (no	eaks)		1		
C21	Driver seat belt					C5	Fuel tank	ĺ				
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness					
C13	First aid kit					C22	Stop arm					
C13	Body fluids kit Defroster					C5	No trailer hitch	regulation.		1		
C6	Heaters						Required by forest of Shovel (securely fast					
	Wheelchair forward facing (post 1993)				1		Axe (securely fasten			1		
*Page ni	umber reference, Standards for School Buses in N						required to wear lap/shoul	der belts - cutter a		driver.	1	1
**Does r	ot apply. ***New buses ordered after 08/15/02.**	***Based	on origi	nal capa	city listed	on the m	anufacturers certification	tag found inside th	ne bus.			
On fi	st inspection, this bus is:					On re	einspection, this bus	is:				
	Approved						Approved					
	Not Approved						Not Approved					
Insped	eting Patrol Officer:					Inspe	cting Patrol Officer:					
Badge No. Date Badge No.				e No.		Date						
	cure of District Official					Date	-					
3												



Date

Signature of District Official

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVBBPLP8PH527309 1993 6133 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* **1HVBBPLPXPH527313** 1993 6126 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date

Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVBBPLPXPH527344 1993 6132 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ☐ Forward Facing ✓ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Interior mirror

Speedometer

Driver seat belt

Fire extinguisher (5 lbs)

Wheelchair forward facing (post 1993)

Steering gear

Body fluids kit

First aid kit

Defroster

Heaters

Brakes

C6

C13

C13

C11

C6

C20

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena, MT 59620-2501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 8501 2GBHG31K6L4108053 1990 Bus Type: (see ? for definition) Chassis Make Body Make **✓** A  $\square$  B  $\Box$  C  $\Box$  D Chevrolet **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\*

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:			
Approved		Approved			
Not Approved		Not Approved			
Inspecting Patrol Officer:		Inspecting Patrol Officer:			
Badge No.	Date	Badge No.	Date		
Signature of District Official		Date			

C17

C22

C5

C4

Identification - rear

Fuel tank

Stop arm No trailer hitch

Cleanliness

Exhaust system (no leaks)

Tires (2/32" rear - 4/32" front min.)

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 2GBHG31K8L4108409 1990 8551 Bus Type: (see ? for definition) Chassis Make Body Make ✓ A □ B □ C  $\Box$  D **Bluebird** Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 2GDHG31K2H4507377 1987 8557 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  B  $\square$  C **✓** A  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ☐ Forward Facing ✓ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 2GDHG31M0G4505496 1986 8553 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  B  $\square$  C **✓** A  $\Box$  D Ward **GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ☐ Forward Facing ✓ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 2GDHG31M4G4505324 1986 8552 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  B  $\square$  C **✓** A  $\Box$  D Ward **GMC** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ☐ Forward Facing ✓ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date

Date

Date

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highway Patrol as soon as all defects are corrected.																
	actions to OPI from School Districts sous has been sold, retired, or is no longer		rice. Ple	ase (	delete it fr	om OPI	's records.									
☐ Ple	ase make corrections noted below. Don't	black ou	it the err	or, O	PI may ne	eed to re	ead it to make the corre	ection.								
OPI County # and County Name						Distri	ct Name									
07 Cascade							Gre	at Falls F	Public 9	chle						
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen		at i alis i	Rated C		****					
V 01110	io i.b. iii (viiv) Entilo ivaliibol		""		oui	2.0011	00 <i>II</i>		riaioa c	apaony						
	4DRBRAAP13B951764			20			1811				71					
Chas	sis Make				Body Mal	ке		Bus Type	: (see ? fo	e ? for definition)						
	International					0	ther	$\Box$ A	⊒в 9	✓ C	$\Box$ D					
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?											
							a Fasina - M N	a4 A m m li a .	مامام							
☐ Y			orward					ot Applica								
Type	of Fuel:	Is Bu	ıs:	Distr	ict Owned	✓ C	ontractor Owned If co	ontractor ow	ned, cont	tractor's	name i	S:				
$\Box$ G	as 🗹 Diesel 🗌 Other						Big Sky Bus	Lines								
					INCDE	CTION	2.3 0.1, 20.0									
		тс	BE FIL	LED	_		GHWAY PATROL									
	This	inspect	ion is for		<b>✓</b> 1s	t semes	ster 2nd semes	ster								
		·	Appro				_				App	roved				
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in			Yes	No	NA	Corr			
No.*	for School Buses in Montana			**		No.*	for School Bus		ına			**	<u> </u>			
C17	Identification - front					C34	Belt cutter **** attach	ed				<u> </u>				
C18	Head lamps	1				C18	Interior lamps					—	+			
C10 C18	Color Turn signal lamps - front					C18 C21	Ceiling - interior Seating					+	+			
C18	Turn signal lamps - from Turn signal lamps - side (post 1987)	1				C14	Floor					$\vdash$	+			
C18	Red amber signals - front					C9	Aisle					<del>                                     </del>	+			
C18	Marker lamps - front					C22	Tools - storage					<del>                                     </del>	+			
C18	Windshield					C24	Windows									
C24	Windshield wipers					C13	Warning device									
C20	Exterior mirrors					C13	Buzzer emergency do	oor								
C3	Battery					C12	Emergency door									
C4	Generator or alternator					C18	Red amber signals -					Ļ				
C11	Service door					C18	Turn signal lamps - re	ear				<u> </u>				
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear				-	<del></del>	+			
C20	Interior mirror	<del> </del>				C19	Strobe light - rear ***					┼─	+			
C6	Speedometer	<del> </del>				C17	Identification - rear						+			
C2	Brakes					C4	Exhaust system (no l	eaks)					+			
C21	Driver seat belt					C5	Fuel tank	,								
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	n.)							
C13	Fire extinguisher (5 lbs)						Cleanliness					<u> </u>				
C13	First aid kit					C22	Stop arm					<b>↓</b>				
C13	Body fluids kit					C5	No trailer hitch	1.4				<u> </u>				
C11 C6	Defroster Heaters						Required by forest r Shovel (securely faste					┼	+			
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene					<del>                                     </del>	+			
	umber reference, Standards for School Buses in I	Montana (	2002 Edit	ion).	****Bus dri	vers are r			ter attache	d nearby	driver.					
	not apply. ***New buses ordered after 08/15/02.*															
On fi	st inspection, this bus is:					On re	einspection, this bus	is:								
	Approved						Approved									
	Not Approved						Not Approved									
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:									
											-		_			
	No	Date				Badge No Date										
Signa	ture of District Official					Date										



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Tilgriway Fation as sour as an defects are corrected.													
Instru	ections to OPI from School District:												
	s bus has been sold, retired, or is no longe												
☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, C	PI may n	need to read it to make the correction.							
OPI (	County # and County Name					District Name							
07 Cascade							Gree	at Falls F	Public S	Schle			
Vehicle I.D. # (VIN) - Entire Number Model Year						Licen		at i alis i	Rated C		****		
VOITIC	ie i.b. // (Viiv) Entire Namber		10100	101 1	oui	Liocii	30 II		raioa c	Japaony			
	X1GBJE1P7MV100651			19	92		8522				66		
Chas	sis Make				Body Mal	ке		Bus Type	: (see ? fo	or defini	tion)		
	Chevrolet					Rlu	ebird	$\Box$ A	⊒в [	<b>✓</b> C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift I	Equipped?		ebiid						
_							- · -						
☐ Y			orward					ot Applica					
Type	of Fuel:	Is B	us:	Distr	rict Owned	Co	ontractor Owned If co	ntractor ow	ned, cont	tractor's	name	is:	
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
							Dig Sky Dus	LIIIES					
		T	DE EII	ı ED		CTION	GHWAY PATROL						
	This		ion is for			t semes		tor					
	11113	шэрссі	Appro			Comos	Zila Scilles	otoi			Ann	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t	he Standar	ds	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Buse					**	
C17	Identification - front					C34	Belt cutter **** attache	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor					<b>-</b>	
C18	Red amber signals - front					C9 C22	Aisle storage					_	-
C18	Marker lamps - front Windshield					C24	Tools - storage Windows					+-	+
C24	Windshield wipers					C13	Warning device					+	+
C20	Exterior mirrors					C13	Buzzer emergency do	or					
C3	Battery	1				C12	Emergency door					+	+
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ar					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear					<u> </u>	
C20	Interior mirror					C19	Strobe light - rear ***					<u> </u>	
C6	Speedometer					C17	Identification - rear	aalta)				_	-
C2 C21	Brakes Driver seat belt					C4 C5	Exhaust system (no le	eaks)				+	+
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min	1.)				
C13	Fire extinguisher (5 lbs)	1				-	Cleanliness		/			1	+
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely faste	,					_
C20	Wheelchair forward facing (post 1993)	<u> </u>					Axe (securely fastene	,		<u> </u>	<u> </u>		
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**										driver.		
					,,								
	rst inspection, this bus is: Approved						einspection, this bus Approved	is:					
님	Approved Not Approved						Approved Not Approved						
Inena	cting Patrol Officer:						cting Patrol Officer:						
mspe	Sung ration Officer.					inspec	Jung Fautor Officer.						
Badge	No.	Date _				Badge No Date							
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

	ay Patrol as soon as all defects are correct		11 20-10-	101, 10	ICA. AII	vernicie	s not approved on his	inspection	must be	remspe	cied by	uie				
Instru	ctions to OPI from School District:															
	s bus has been sold, retired, or is no longe		ice. Ple	ase de	elete it fr	om OPI	's records.									
☐ Ple	ase make corrections noted below. Don't	olack ou	ut the err	or, OP	l may ne	eed to re	ead it to make the corr	ection.								
OPI C	County # and County Name					Distri	ct Name									
	07.000000						0	-4 F-U- F	l. !! C	\_ - - -						
07 Cascade       Vehicle I.D. # (VIN) - Entire Number     Model Year				Licen		at Falls F	Rated C		, ****							
venic	ie i.D. # (VIIV) - Entile Nambei		IVIO	uei re	aı	Licen	Se #		Raieu C	apacity	′					
	X1GDJ61ESEV546235			198	4		8455				66					
Chass	sis Make			В	ody Mal	се		Bus Type	: (see ? fo	or defin	ition)	1)				
	GMC					Cari	penter	$\Box$ A	□в 9	<b>✓</b> C	$\Box$ D					
Whee	Chair Lift Equipped?	Whe	el Chair	Lift Ec	quipped?		penter									
✓ Ye	_ `						o Fooing	ot Applied	hla							
							<u>-</u>	ot Applica								
	of Fuel:	Is Bu	us:	Distric	t Owned	C 🗸	ontractor Owned If co	ontractor ow	ned, cont	tractor's	name i	s:				
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines								
		•			INSPE	CTION										
		TC	BE FIL	LED (	_		GHWAY PATROL									
	This	inspect	ion is for		<b>✓</b> 1s	t semes	ster 2nd seme	ster								
			Appro	oved							App	roved				
Page	Items listed in the Standards	Yes	No	NA **	Corr	Page	Items listed in			Yes	No	NA **	Corr			
No.*	for School Buses in Montana			**		No.*	for School Bus		na			**				
C17	Identification - front					C34 C18	Belt cutter **** attach	ed								
C10	Head lamps Color					C18	Ceiling - interior									
C18	Turn signal lamps - front					C21	Seating									
C18	Turn signal lamps - side (post 1987)					C14	Floor									
C18	Red amber signals - front					C9	Aisle									
C18	Marker lamps - front					C22	Tools - storage									
C18	Windshield					C24	Windows									
C24	Windshield wipers					C13	Warning device									
C20	Exterior mirrors					C13	Buzzer emergency d	oor								
C3	Battery Generator or alternator					C12 C18	Emergency door Red amber signals -	roor								
C11	Service door					C18	Turn signal lamps - re									
C6	Head lamp indicator					C18	Stop lamps	Jui								
C6	Horn					C18	Marker lamps - rear				1					
C20	Interior mirror					C19	Strobe light - rear ***									
C6	Speedometer					C17	Identification - rear									
C2	Brakes					C4	Exhaust system (no l	eaks)								
C21	Driver seat belt					C5	Fuel tank		,							
C7	Steering gear Fire extinguisher (5 lbs)	-				C7	Tires (2/32" rear - 4/3 Cleanliness	ı∠" tront min	1.)	-						
C13	First aid kit				1	C22	Stop arm				<u> </u>		1			
C13	Body fluids kit					C5	No trailer hitch									
C11	Defroster					-	Required by forest	egulation:								
C6	Heaters						Shovel (securely fast									
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene									
	umber reference, Standards for School Buses in Not apply. ***New buses ordered after 08/15/02.**										driver.					
		Dase0	i on ongin	аі сара	oity iisted	on the M	anuraciurers certification	ay iourid IIISI	JE UIE DUS.							
	st inspection, this bus is:						einspection, this bus	is:								
	Approved						Approved									
	Not Approved						Not Approved									
Insped	eting Patrol Officer:					Inspe	cting Patrol Officer:									
Badge	No	Date				Badge	e No.			Date						
Signa	ure of District Official					Date										



Fire extinguisher (5 lbs)

Wheelchair forward facing (post 1993)

First aid kit

Defroster

Heaters

Body fluids kit

C13

C13

C11

C6

C20

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena, MT 59620-2501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # X1GDJ6P1BKV514898 1989 8514 66 Bus Type: (see ? for definition) Chassis Make Body Make ПА □в ✓ C  $\Box$  D **GMC** Carpenter Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	

C22

C5

Cleanliness

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)

Stop arm
No trailer hitch



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

	actions to OPI from School District: s bus has been sold, retired, or is no longer	in serv	ica Pla	ase d	oloto it fr	om ∩PI	'e recorde						
	ease make corrections noted below. Don't b							ection.					
	County # and County Name			, -	,	District Name							
	07 Cascade					Great Falls Public Schls							
Vehic	le I.D. # (VIN) - Entire Number		Mod	Model Year License #					Rated Car		/ ****		
	VV4.001.0004V4.0004			400			2522			·			
Chas	XX1GBL6P3MV100204			199		_	8529	Buc Type	(see ? for	dofin	72		
Cnas	sis Make				Body Mak	е							
	Chevrolet					W	/ard	∐ A L	_ B <b>✓</b>	С	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?								
☐ Y		□ F	orward	l Fac	ing [	☐ Aisl	e Facing 🔽 N	ot Applica	ble				
Type of Fuel: Is Bus: District Owne					ct Owned	<b>✓</b> C	ontractor Owned If co	ontractor ow	ned, contra	ctor's	s name	is:	
✓ Gas □ Diesel □ Other							Big Sky Bus	lings					
					INODE	OTION	Dig Oky Dus	LIIICS					
		то	BF FII	I FD (	INSPE		GHWAY PATROL						
	This i	_	ion is for		_	semes	_	ster					
			Appro					010.			App	roved	
Page	Items listed in the Standards	Yes		NA	Corr	Page	Items listed in	the Standar	ds Y	es	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		na			**	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						-
C10 C18	Color Turn signal lamps - front					C18 C21	Ceiling - interior Seating						-
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency d	oor					
C3	Battery					C12	Emergency door						-
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re						-
C6	Head lamp indicator					C18	Stop lamps	cai					
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no	eaks)					
C21	Driver seat belt					C5	Fuel tank	0011 ( 1 '-	`				
C7 C13	Steering gear Fire extinguisher (5 lbs)					C7	Tires (2/32" rear - 4/3 Cleanliness	32" front min	.)				
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest	regulation:					
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
- 3	umber reference, Standards for School Buses in M not apply. ***New buses ordered after 08/15/02.***			- /						earby	/ driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	• No	Date				Badge	e No		D	ate _			
Signa	ture of District Official					Date							
											TR-1	3 Revis	ed 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	Highway Patrol as soon as all defects are corrected.												
Instru	ictions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	er in serv	ice. Pl	ease de	elete it fr	om OPI	's records.						
☐ Ple	ase make corrections noted below. Don't	black ou	ut the er	ror, OF	l may n	eed to read it to make the correction.							
OPI C	County # and County Name					District Name							
	07.0					Creet Falls Bublic Cable							
\/alaia	07 Cascade			1 V -		Great Falls Public Schls License # Rated Capacity *****							
venic	le I.D. # (VIN) - Entire Number		IVIC	del Ye	ar	Licen	se #	Rate	ed Capacity	,			
	XX1GDL7T1P5650024			199	3		3064			71			
Chass	sis Make			Е	ody Mal	се		Bus Type: (see	? for defin	ition)			
0110					DI.	ala i a al	□а □в	✓ C	$\Box$ D				
GMC Wheel Chair Lift Equipped? Wheel Chair Lift Equipped?						ebird							
☐ Ye	es 🗹 No	∐ F	orwar	d Fac	ing	_ Aisl	e Facing 🔛 N	ot Applicable					
Type of Fuel: Is Bus: District Owner			t Owned	✓ C	ontractor Owned If co	ontractor owned, o	contractor's	name	is:				
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Big Sky Bus	Lines					
							big 3ky bus	LIIIES					
		т.	DE EI	LLED		CTION	CUWAY BATBOI						
	Thic	inspect			_	t semes	GHWAY PATROL ster	stor					
	11115	ilispeci		roved	<b>V</b> 18	t semes		Stei		Ann	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus	es in Montana			**		
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps				<u> </u>		
C10	Color					C18	Ceiling - interior				<del> </del>		
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)					C21 C14	Seating Floor				+		
C18	Red amber signals - front				1	C14	Aisle				+		
C18	Marker lamps - front				1	C22	Tools - storage				+		
C18	Windshield					C24	Windows				1		
C24	Windshield wipers					C13	Warning device				1		
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door				<u> </u>		
C4	Generator or alternator					C18	Red amber signals -				<del> </del>		
C11	Service door					C18	Turn signal lamps - re	ear			+		
C6 C6	Head lamp indicator Horn				+	C18	Stop lamps Marker lamps - rear				+		
C20	Interior mirror				1	C19	Strobe light - rear ***				+		
C6	Speedometer				1		Identification - rear				1		
C2	Brakes					C4	Exhaust system (no l	eaks)			1		
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.)			<u> </u>		
C13	Fire extinguisher (5 lbs)					000	Cleanliness				<u> </u>		
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch		_		<del>                                     </del>		
C11	Defroster Defroster					0.0	Required by forest i	regulation:			+		
C6	Heaters						Shovel (securely fast				1		
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene				1		
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**									driver.			
		Daset	. o., ongi	.а. оара	ony noteu				~ 40.				
	st inspection, this bus is:						einspection, this bus	IS:					
	Approved Not Approved						Approved Not Approved						
	• •						cting Patrol Officer:						
	cting Patrol Officer:												
Badge		Date					e No		Date				
Signa	ture of District Official					Date							
						1							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Great Falls Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # XXXXXXE34HHB66216 1976 8554 Bus Type: (see ? for definition) Chassis Make Body Make **✓** A □в □с  $\Box$  D Other Ford Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Big Sky Bus Lines INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Cascade Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* **1BAAECSH5NF049364** 1992 1526 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	ngimay i atroi ao ooon ao an aolosto are conocioa.												
Instru	actions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ase	delete it fr	om OPI	s records.						
☐ Ple	ease make corrections noted below. Don't	black ou	ut the err	or, C	OPI may ne	eed to read it to make the correction.							
OPI C	County # and County Name					District Name							
							_						
	07 Cascade					Cascade Public Schools							
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Y	'ear	License # Rated Capacity *****							
	1BAANCPA6YF091851			19	99		1902			84			
Chas	sis Make			Ť	Body Mak	e	1002	Bus Type: (see ?	for defin				
0					20a)a.								
Bluebird							ebird	□ A □ B	□с	<b>✓</b> D			
Wheel Chair Lift Equipped?  Wheel Chair Lift Equipped					Equipped?	1							
☐ Y	es 🗹 No	I □ F	orwar	d Fa	acina	Aisl	e Facing 🗹 N	ot Applicable					
	of Fuel:						ontractor Owned If co		ntractor's	name	ie:		
		13 0	us. 🔻	Disti	not Owned		ontractor Owned in co	intractor owned, co	TITI ACTOR S	Hame	13.		
□G	as ☑ Diesel ☐ Other												
					INSPE	CTION							
		TC	BE FIL	LED			GHWAY PATROL						
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ter 2nd semes	ster					
		·	Appr				_			App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus	es in Montana			**		
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery	<u> </u>				C12	Emergency door		-	<u> </u>	<u> </u>	-	
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6 C6	Head lamp indicator Horn	<del> </del>				C18	Stop lamps Marker lamps - rear		-	<u> </u>	1		
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes	<del> </del>				C4	Exhaust system (no le	eaks)	1		1		
C21	Driver seat belt					C5	Fuel tank	ou.io,					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)					
C13	Fire extinguisher (5 lbs)						Cleanliness	,					
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely faste	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**									driver.			
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
H	Not Approved						Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
-	-												
Badge	e No	Date				Badge	No		_ Date _				
Signa	ture of District Official				<del></del>	Date						<del></del>	



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
	s bus has been sold, retired, or is no longe ase make corrections noted below. Don't							ection.				
	County # and County Name						ct Name					
	07 Cascade						Cas	cade Public S	chools			
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen			d Capacity	/ ****		
	1FDJE37F2SH28726			199	5		1736 18					
Chas	sis Make				Body Mal	ке	1730	Bus Type: (see '	? for defin			
	Ford				,		ıebird	<b>✓</b> A □ B	□с	□ D		
Whee	el Chair Lift Equipped?	Whe	eel Chair	· Lift E	quipped?		lebiid					
☐ Y	es 🗹 No	$\Box$	orwar	d Fac	ina	Aisl	e Facing 🔽 N	ot Applicable				
	of Fuel:						ontractor Owned If co		ontractor's	name	is:	
□G		.0.2	uo. 🚺	2.0						,		
	as ☑ Diesel ☐ Other											
		-	2 DE EU		_	CTION	CLIMAY BATBOL					
	This		tion is fo			t semes	GHWAY PATROL ster	eter				
	11115	inspec		oved	<b>▼</b> 18	i semes	Stei Zhu Seille:	Stei		Apr	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus				**	
C17	Identification - front Head lamps	1	+			C34 C18	Belt cutter **** attach	ed		<u> </u>	+	
C10	Color		<del> </del>			C18	Interior lamps Ceiling - interior				+	+
C18	Turn signal lamps - front		1			C21	Seating					
C18	Turn signal lamps - side (post 1987)					C14	Floor					
C18	Red amber signals - front					C9	Aisle					
C18	Marker lamps - front					C22	Tools - storage					
C18	Windshield					C24	Windows					
C24	Windshield wipers					C13	Warning device					
C20	Exterior mirrors					C13	Buzzer emergency do	oor				
C3	Battery	1	<u> </u>		1	C12	Emergency door		_		+	<del> </del>
C4 C11	Generator or alternator Service door		1			C18	Red amber signals - Turn signal lamps - re		-		+	+
C6	Head lamp indicator					C18	Stop lamps	edi .				
C6	Horn	1	+		1	C18	Marker lamps - rear		_		+	+
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer					C17	Identification - rear					
C2	Brakes					C4	Exhaust system (no l	eaks)				
C21	Driver seat belt					C5	Fuel tank					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)				
C13	Fire extinguisher (5 lbs)					000	Cleanliness					
C13	First aid kit Body fluids kit	1	<u> </u>		1	C22	Stop arm No trailer hitch		_		+	<del> </del>
C13	Defroster		1			C5	Required by forest r	ogulation:	-		+	+
C6	Heaters						Shovel (securely fast				1	
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene				+	
*Page n	umber reference, Standards for School Buses in Inot apply. ***New buses ordered after 08/15/02.**						required to wear lap/should	der belts - cutter attac		driver.		1
	rst inspection, this bus is:						einspection, this bus					
	Approved						Approved	ia.				
片	Not Approved						Not Approved					
	cting Patrol Officer:					Inspe	cting Patrol Officer:					
Badge		Date					e No.		Date			
	ture of District Official					Date	<u> </u>					
5												
										TR-	13 Revis	ed 11/04



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correc	ted.											
Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
	ase make corrections noted below. Don't	black ou	ut the err	or, OF	PI may ne								
OPI C	County # and County Name					District Name							
	07 Cascade					Cascade Public Schools							
Vehic	le I.D. # (VIN) - Entire Number		Мо	Model Year			se#		Rated C	Capacity	, ****		
	1FDJE37F4SHB28727			199	95		1737				18		
Chas	sis Make		<u> </u>		Body Mal	е		Bus Type	e: (see ? f	or defini			
Foud				DI	ahird	<b>✓</b> A	□ B [	□с	$\Box$ D				
Whee	Ford el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?		ıebird						
							o Fooine	at Annlia	ماطه				
☐ Ye			orwar					ot Applic					
• •	of Fuel:	IS B	us: 🗸	DISTRIC	ct Owned		ontractor Owned If co	ontractor ov	vnea, con	tractors	name	IS:	
□G	as ☑ Diesel ☐ Other												
					INSPE	CTION							
					OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ster 2nd seme	ster					
D	Harris Patadia tha Otandanda	17		oved	10	l D	I Borne Percel Se	the Oterale		1./		roved	10
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front  Marker lamps - front					C9 Aisle C22 Tools - storage					-		
C18	Windshield	1				C24	Windows						+
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20 C6	Interior mirror Speedometer					C19 C17	Strobe light - rear *** Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank	ouno)					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front mi	n.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11 C6	Defroster						Required by forest i						
C20	Heaters Wheelchair forward facing (post 1993)						Shovel (securely fast Axe (securely fastene						
*Page n	umber reference, Standards for School Buses in						equired to wear lap/shoul	der belts - cu			driver.		1
	not apply. ***New buses ordered after 08/15/02.*												
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No.			Date			
	ture of District Official					Date				=			
- 3													



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Cascade Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1FDSE35F53HB65813 2003 2234 Bus Type: (see ? for definition) Chassis Make Body Make **✓** A □в  $\Box$  C  $\Box$  D Ford Ford Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Tilgilw	ay Fatioi as soon as all defects are correct												
Instru	ctions to OPI from School District:												
Thi	☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, O	PI may ne	need to read it to make the correction.							
OPI 0	County # and County Name					District Name							
	•												
	07 Cascade						Case	cade Public					
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen	se#	R	ated Capacit	y ****			
1FDSE4SF4YHB35169 2000					4000			20					
Chas	1FDSE4SF4YHB35169						1266	Bus Type: (se	oo 2 for dofin	28			
Chas	sis Make				Body Mal	ke		,, ,		iitiOH)			
	Ford					Blu	ebird	✓ A 🗆 I	в 🗆 С	$\Box$ D			
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?								
		1 – .				^:_I	. Fasina	- 4 - A - 3 1 1 - 1	_				
☐ Ye			orward					ot Applicable					
Туре	of Fuel:	Is B	us: 🗸	Distr	ict Owned	I 🗌 C	ontractor Owned If co	ntractor owned	d, contractor	s name	is:		
□G	as ☑ Diesel ☐ Other												
						CTION							
							GHWAY PATROL						
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ter 2nd semes	ster					
			Appro	oved						App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t		Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Buse				**		
C17	Identification - front					C34	Belt cutter **** attache	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14 Floor							
C18	Red amber signals - front					C9 Aisle							
C18	Marker lamps - front					C22 Tools - storage							
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors	<u> </u>				C13	Buzzer emergency do	oor		-	-		
C3	Battery					C12 C18	Emergency door						
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re					-	
C6	Head lamp indicator	<u> </u>				C18	Stop lamps	aı		-	1		
C6	Horn	<u> </u>				C18	Marker lamps - rear			-	1		
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no le	aks)					
C21	Driver seat belt	1				C5	Fuel tank	ound)					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)					
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely faste	•					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	d)					
*Page n	umber reference, Standards for School Buses in I	Montana (	(2002 Edit	ion).	****Bus dri	vers are r	equired to wear lap/should	ler belts - cutter a	attached nearb	y driver.	•		
**Does r	not apply. ***New buses ordered after 08/15/02.**	***Basec	d on origina	al cap	acity listed	on the m	anufacturers certification to	ag found inside th	he bus.				
On fi	rst inspection, this bus is:					On re	inspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
mspec	ung ration officer.				<del></del>	inspec	oung Faului Officer.					<del></del>	
Badge	• No	Date				Badge	• No		Date				
	ture of District Official					Date							
5 -													



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Cascade Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBJG31F311197699 2001 2219 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  B  $\square$  C **✓** A  $\Box$  D Chevrolet Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ✓ Forward Facing ☐ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is:

On first inspection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.
Date
Badge No.
Date
TR-13 Revised 11/04



## MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Cascade Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBL7T1J9WJ105127 1998 1828 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Chevrolet **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch Defroster C11 Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
<b>-</b>			
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	



C6

C13

C13

C11

C6

C20

Speedometer

Driver seat belt

Fire extinguisher (5 lbs)

Wheelchair forward facing (post 1993)

Steering gear

Body fluids kit

First aid kit

Defroster

Heaters

Brakes

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena, MT 59620-2501

## MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Cascade Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBRAAMX2B941608 2002 1221 Bus Type: (see ? for definition) Chassis Make Body Make ПА ПВ ✓ C  $\Box$  D International International Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:				
Approved		Approved				
Not Approved		Not Approved				
Inspecting Patrol Officer:		Inspecting Patrol Officer:				
Badge No.	Date	Badge No.	Date			
Signature of District Official		Date				
C.g.,						

C17

C22

C5

C4

Identification - rear

Fuel tank

Stop arm

Cleanliness

No trailer hitch

Exhaust system (no leaks)

Tires (2/32" rear - 4/32" front min.)

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	-,												
Instru	ctions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	r in serv	rice. Ple	ase	delete it fr	om OPI	s records.						
☐ Ple	ase make corrections noted below. Don't	black ou	it the err	or, C	PI may ne	eed to read it to make the correction.							
OPI C	County # and County Name					District Name							
							_		_				
	07 Cascade							cade Public So					
Vehicle I.D. # (VIN) - Entire Number Model Year				Licen	se #	Rated	I Capacity	/ *****					
	1T88U3B21T1133824			19	96		1692			84			
Chas	sis Make				Body Mak	ie .		Bus Type: (see ?	for defin				
										✓ D			
	Other						omas	□ A □ B	□с	<b>V</b> D			
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	Equipped?	?							
☐ Ye	es 🗹 No	☐ F	orwar	d Fa	cing [	☐ Aisl	e Facing 🗹 N	ot Applicable					
Type	of Fuel:						ontractor Owned If co		ontractor's	name	is:		
• •		10 5	uo. 👣	D1011	101 0 111100		omicolor ownou in oc	miliaotor ownou, oc	onti dotor c	rianio			
$\Box$ G	as ☑ Diesel ☐ Other												
					INSPE	CTION							
		TC	BE FIL	.LED			GHWAY PATROL						
	This	inspect	ion is foi	:	<b>✓</b> 1s	t semes	ter 2nd semes	ster					
			Appr	oved						App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in		Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus				**		
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps				-		
C10	Color	1				C18	Ceiling - interior		_	1	1		
C18	Turn signal lamps - front					C21 C14	Seating						
C18	Turn signal lamps - side (post 1987)  Red amber signals - front	1				C14			+	1	1		
C18	Marker lamps - front					C22							
C18	Windshield	+				C24	ÿ		+	1	1		
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors	1				C13 Buzzer emergency door		oor	+	1	1		
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no le	eaks)			-		
C21	Driver seat belt					C5	Fuel tank	2" front min \	_		-		
C7 C13	Steering gear Fire extinguisher (5 lbs)	+				C7	Tires (2/32" rear - 4/3 Cleanliness	∠ 11UHLHIII.)		1	1	1	
C13	First aid kit					C22	Stop arm		_				
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster					-	Required by forest r	egulation:					
C6	Heaters						Shovel (securely faste	_					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
*Page ni	umber reference, Standards for School Buses in Into apply. ***New buses ordered after 08/15/02.**									driver.	-	-	
	rst inspection, this bus is:						inspection, this bus						
	Approved						Approved	13.					
	Not Approved						Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
spec						spet							
Badge	• No.	Date				Badge	No		Date			<u></u>	
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	Highway Patrol as soon as all defects are corrected.											
Instru	ictions to OPI from School District											
	This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.											
_ Ple	ase make corrections noted below. Don't	black ou	ut the er	ror, OF	PI may n	eed to re	ead it to make the corr	ection.				
OPI C	County # and County Name					District Name						
									_			
07 Cascade						cade Public So						
Vehicle I.D. # (VIN) - Entire Number Model Year				Licen	se#	Rated	Capacity	/ ****				
	1T88U3B2831123808			200	3		2076			84		
Chas	sis Make				Body Mal	ке		Bus Type: (see ?	for defin	_		
					,			□А□В	□с	✓ D		
100	Thomas	1 147	1.01	1.00 =			omas			<u> </u>		
whee	el Chair Lift Equipped?	Whe	el Chai	Lift E	quipped?	,						
□ Ye	es 🗹 No	□ F	orwar	d Fac	ing	☐ Aisl	e Facing 🛮 🗹 N	ot Applicable				
Туре	of Fuel:	Is B	us: 🗸	Distric	ct Owned	d C	ontractor Owned If co	ontractor owned, co	ntractor's	name	is:	
□G	as ☑ Diesel ☐ Other											
	as 🛂 Diesei 🗆 Other											
					INSPE	CTION						
							GHWAY PATROL					
	This	inspect			<b>✓</b> 1s	t semes	ster 2nd seme	ster				
_		Tv.		oved	10	-				_ ' '	roved	T <sub>0</sub>
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus		Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach				+	
C18	Head lamps					C18	Interior lamps	Cu	+	1	+	
C10	Color					C18	Ceiling - interior				†	
C18	Turn signal lamps - front					C21	Seating				1	
C18	Turn signal lamps - side (post 1987)					C14 Floor						
C18	Red amber signals - front					C9 Aisle						
C18	Marker lamps - front					C22 Tools - storage						
C18	Windshield					C24 Windows					<u> </u>	
C24	Windshield wipers					C13 Warning device					<u> </u>	
C20	Exterior mirrors				-	C13	Buzzer emergency de	oor	-		<b>├</b> ──	
C3 C4	Battery Generator or alternator	1				C12 C18	Emergency door Red amber signals -	rear	+		┼──	
C11	Service door					C18	Turn signal lamps - re				+	
C6	Head lamp indicator					C18	Stop lamps	<u> </u>			+	
C6	Horn					C18	Marker lamps - rear					
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer						Identification - rear					
C2	Brakes					C4	Exhaust system (no l	eaks)			<u> </u>	
C21	Driver seat belt					C5	Fuel tank	00   (	_		<del> </del>	
C7 C13	Steering gear					C7	Tires (2/32" rear - 4/3 Cleanliness	32" front min.)			+	
C13	Fire extinguisher (5 lbs) First aid kit					C22	Stop arm				+	
C13	Body fluids kit					C5	No trailer hitch		+		+	
C11	Defroster						Required by forest r	egulation:			†	
C6	Heaters						Shovel (securely fast	ened)			1	
C20	Wheelchair forward facing (post 1993)				L		Axe (securely fastene	,				
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.*									driver.		
On fi	st inspection, this bus is:					On re	einspection, this bus	is:				
	Approved						Approved					
	Not Approved						Not Approved					
Inspec	eting Patrol Officer:					Inspe	cting Patrol Officer:					
Badge		Date		_	_		e No.		Date			
	ture of District Official	Date				Date			_ Juit			
Jigila	o or product official					Jule						



C6

C20

Heaters

Wheelchair forward facing (post 1993)

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Cascade Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 4DRBRABM44B972047 2004 2160 Bus Type: (see ? for definition) Chassis Make Body Make ПА Пв ✓ C  $\Box$  D Other International Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation:

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date

Badge No.

Date

Date

Date

Shovel (securely fastened)

Axe (securely fastened)



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Centerville Public Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAAHCPA71F096845 1994 1593 Bus Type: (see ? for definition) Chassis Make Body Make ПА ПВ ✓ C  $\Box$  D Ford **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL

#### ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Steering gear Tires (2/32" rear - 4/32" front min.) Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch Defroster C11 Required by forest regulation: C6 Heaters Shovel (securely fastened) Wheelchair forward facing (post 1993) Axe (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Dadas Na	But	<b>-</b>	
Badge No.	Date	Badge No.	Date
Signature of District Official	Date	Date	Date



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

riigiiw	ay Patrol as soon as all defects are correct	leu.												
	octions to OPI from School Districts s bus has been sold, retired, or is no longe		/ice. Ple	ase c	lelete it fr	om OPI	s records.							
☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, O	PI may n	eed to re	ead it to make the corre	ection.						
OPI C	OPI County # and County Name						District Name							
	07 Cascade						Cen	terville F	Public S	Schls				
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ear	Licen	se#		Rated C	Capacity	*****			
	1DGD6P1XFGV532079			198	36		1145				40			
Chass	sis Make				Body Mal	ке		Bus Type	: (see ? f	or defin	ition)			
	GMC					Blu	ebird	<b>✓</b> A	⊒ в      [	□с	$\Box$ D			
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?									
✓ Ye	es 🗆 No		orward				e Facing	ot Applica	able					
	of Fuel:						ontractor Owned If co			tractor's	name	is:		
G									ŕ					
	as Diesei - Othei													
		_				CTION								
	This						GHWAY PATROL							
	Inis	Inspect	ion is for Appr		<b>V</b> 18	t semes	ter 2nd semes	ster			Ann	roved		
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr	
C17	Identification - front					C34	Belt cutter **** attach		ша			┼──		
C18	Head lamps					C18	Interior lamps	cu				+		
C10	Color					C18	Ceiling - interior					1		
C18	Turn signal lamps - front					C21	Seating					1		
C18	Turn signal lamps - side (post 1987)					C14	Floor					1		
C18	Red amber signals - front					C9	Aisle					+		
C18	Marker lamps - front					C22	Tools - storage					+		
C18	Windshield					C24	Windows					1		
C24	Windshield wipers					C13	Warning device					1		
C20	Exterior mirrors	1				C13	Buzzer emergency do	oor		1		1		
C3	Battery					C12	Emergency door							
C4	Generator or alternator					C18	Red amber signals -	rear				1		
C11	Service door					C18	Turn signal lamps - re					1		
C6	Head lamp indicator					C18	Stop lamps					1		
C6	Horn					C18	Marker lamps - rear					1		
C20	Interior mirror					C19	Strobe light - rear ***							
C6	Speedometer					C17	Identification - rear					1		
C2	Brakes					C4	Exhaust system (no le	eaks)						
C21	Driver seat belt					C5	Fuel tank							
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mir	າ.)					
	Fire extinguisher (5 lbs)						Cleanliness							
C13	First aid kit					C22	Stop arm					<b>↓</b>		
C13	Body fluids kit					C5	No trailer hitch					<b>↓</b>		
C11	Defroster						Required by forest r							
C6	Heaters						Shovel (securely faste	,						
C20	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in I	Mon+-	(2002 5 "	tion.	*****	1075 -	Axe (securely fastene		tor ctt. I	d = '	مامان	<u> </u>		
**Does r	umber reference, Standards for School Buses in I lot apply. ***New buses ordered after 08/15/02.*'	viontana '***Based	(2002 Ean d on origin	tion). al cap	acity listed	vers are r on the m	equired to wear lap/should anufacturers certification t	aer beits - cui ag found insi	tter attache de the bus	ed nearby	ariver.			
On fir	st inspection, this bus is:					On re	inspection, this bus	is:						
	Approved					l	Approved							
	Not Approved						Not Approved							
	eting Patrol Officer:						cting Patrol Officer:							
Badge	No	Date				Badge No Date								
Signat	ure of District Official	_		-		Date				_				



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Centerville Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GDHG31K4RF504895 1994 1615 Bus Type: (see ? for definition) Chassis Make Body Make **✓** A □в □с  $\Box$  D **GMC Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Date

Signature of District Official

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Centerville Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBBABPOWH23655 1998 726 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



## **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Hignw	ay Patrol as soon as all defects are correcte	ea.											
	uctions to OPI from School District: is bus has been sold, retired, or is no longer	in servi	ice Plea	ise.	delete it fr	nm OPI	's records						
	ease make corrections noted below. Don't be		action										
	County # and County Name	nack ou	t tile elle	, C	or i iliay ile	District Name							
	07 Cascade						Cen	terville l	Public S	chis			
Vehic	cle I.D. # (VIN) - Entire Number		Mod	el \	/ear	Licen			Rated C		****		
	1HVBBABPWH523654			10	998		566			. ,	60		
Chas	sis Make		<u> </u>	T	Body Mak	<u> </u>	300	Bus Type	e: (see ? fo	or defini			
Ondo					Body Mai			□ A	•	✓ C	□ D		
Whee	International el Chair Lift Equipped?	Whee	el Chair I	ift	Equipped?		omas						
□ Y			orward			_	e Facing <b>☑</b> N	ot Applia	abla				
	of Fuel:				rict Owned			ot Applic		ro otorio	2022	io.	
		IS Du	is. 🗸 L	JISI	nct Owned		ontractor Owned If co	miracior ov	vnea, cont	raciors	name	S.	
□G	as 🗹 Diesel 🗌 Other												
						CTION							
	Th:-	_				THE HI t semes	GHWAY PATROL						
	Inis	inspection	on is for: Appro		_	t semes	ster	ster			Ann	roved	
Page	Items listed in the Standards	Yes		VA	Corr	Page	Items listed in	the Standa	rds	Yes	No	NA	Corr
No.*	for School Buses in Montana	100	,	**	0011	No.*	for School Bus			100	110	**	0011
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior					<u> </u>	
C18	Turn signal lamps - front					C21	Seating					ـــــ	
C18	Turn signal lamps - side (post 1987)					C14	Floor					<u> </u>	
C18	Red amber signals - front					C9 C22	Aisle					<b>├</b> ──	+
C18	Marker lamps - front Windshield		-			C24	Tools - storage Windows					┼──	+
C24	Windshield wipers					C13	Warning device					+	+
C20	Exterior mirrors					C13	Buzzer emergency do	or				<del>                                     </del>	+
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps					<b>↓</b>	
C6	Horn					C18	Marker lamps - rear					—	
C20 C6	Interior mirror					C19 C17	Strobe light - rear *** Identification - rear					$\vdash$	_
C2	Speedometer Brakes					C17	Exhaust system (no le	aaks)				+-	+
C21	Driver seat belt					C5	Fuel tank	ouno)				+	+
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front mi	n.)			<b>T</b>	1
C13	Fire extinguisher (5 lbs)						Cleanliness		,				
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch					ــــــ	
C11	Defroster						Required by forest r	_				₩	
C6 C20	Heaters Wheelchair forward facing (post 1993)						Shovel (securely fastene Axe (securely fastene	,				$\vdash$	_
	umber reference, Standards for School Buses in M	lontana (2	2002 Editio	on).	****Bus driv	ers are i		,	tter attached	d nearby	driver.		
	not apply. ***New buses ordered after 08/15/02.***									- ,			
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	e No	Date				Badge	e No			Date			
Signa	ture of District Official					Date							
-													
											TR-1	3 Revis	ed 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.						<u>'</u>					
Instru	uctions to OPI from School District	•											
	s bus has been sold, retired, or is no longe												
	ease make corrections noted below. Don't		ection.										
OPI (	County # and County Name					Distri	ct Name						
	07 Cascade						Cer	nterville Pu	blic Schl	5			
Vehic	le I.D. # (VIN) - Entire Number		Мо	odel Ye	ar	Licen			Rated Capac				
	47742227014507040			400			4000						
Choo	1T7A33872L1587818 sis Make			199	Body Mal	<b>'</b>	1380	Bus Type: (s	see 2 for det	66			
Crias	sis iviake				ouy iviai	(e		l `` _`					
	Other						omas	□ A □	В □С	✓ D			
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped?	)							
$\square$ Y	es 🗹 No		orwar	d Fac	ing	☐ Aisl	e Facing 🔽 N	lot Applicab	le				
Туре	of Fuel:	Is B	us: 🗸	Distric	t Owned	l C	ontractor Owned If co	ontractor owne	ed, contracto	r's name	is:		
	as ☑ Diesel ☐ Other												
	as 🗷 Diesei 🗆 Other												
						CTION							
	Th:-				_		GHWAY PATROL	-4					
	Inis	inspect		or: roved	<b>✓</b> 18	t semes	ster 2nd seme	ster		Λn	oroved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	Nο	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus				**		
C17	Identification - front					C34	Belt cutter **** attach	ned					
C18	Head lamps					C18	Interior lamps			_			
C10	Color				+	C18	Ceiling - interior			-			
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)				+	C21	Seating Floor			+			
C18	Red amber signals - front				+	C9	Aisle			+			
C18	Marker lamps - front				1	C22	Tools - storage			+			
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3 C4	Battery Generator or alternator				-	C12 C18	Emergency door Red amber signals -	roor		-			
C11	Service door					C18	Turn signal lamps - re			+			
C6	Head lamp indicator				1	C18	Stop lamps	<u> </u>		+			
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer						Identification - rear						
C2 C21	Brakes Driver seat belt				1	C4 C5	Exhaust system (no l	eaks)		-			
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min )		+			
C13	Fire extinguisher (5 lbs)					<u> </u>	Cleanliness	<u>, , , , , , , , , , , , , , , , , , , </u>					
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest	_					
C6	Heaters Who clobair forward facing (past 1992)						Shovel (securely fast						
C20 *Page n	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in	Montana i	(2002 Ed	ition). *	***Bus dri	vers are r	Axe (securely fastend required to wear lap/shoul	,	attached near	by driver			
	not apply. ***New buses ordered after 08/15/02.**									.,			
On fi	rst inspection, this bus is:					On re	inspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Rado	• No	Date				Rados	e No		Date				
	ture of District Official	Date				Date			Date				
Gigila	tare of District Official					Date							



Inspecting Patrol Officer:

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Centerville Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 3916 1994 1593 Bus Type: (see ? for definition) Chassis Make Body Make ПА ПВ ✓ C  $\Box$  D Ford **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved

Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highwa	ay Patrol as soon as all defects are correc	ted.											
Instru	Instructions to OPI from School District:												
	This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
	ase make corrections noted below. Don't							ection.					
	County # and County Name					District Name							
0110	odity # and oddity Name												
	07 Cascade					Centerville Public Schls							
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen	se#		Rated C	Capacity	****		
	411744741/0001/00045												
	4UZAAXAK83CK93915 2003						2077	D T	/ O f	l - C - '	72		
Chassis Make Body Ma					Body Mal	се		Bus Type:	: (see ? 1	or aetini	tion)		
	Freightliner					The	omas	$\Box$ A	☐ B	✓ C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?		<u> </u>	<u>l</u>					
				J = -	· · · ·	¬ ∧:-ı	- Fi						
☐ Ye			orwar					ot Applica					
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	ı	ontractor Owned If co	ontractor ow	ned, con	tractor's	name	s:	
□ G	as ☑ Diesel ☐ Other												
					_	CTION	01 1144 AV DATDOI						
	<del>-</del>						GHWAY PATROL						
	Ihis	inspect	ion is fo		<b>✓</b> 1s	t semes	ster 2nd seme	ster					
Dow-	Itomo liotad in the Ctandard	Vac	Appr		Co	Done	المعمم المدعا ا	tha Ctar-dr	do	Vac		roved NA	Corr
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach		<u>.</u>			+	
C18	Head lamps	1				C18	Interior lamps	cu		1		+	
C10	Color					C18	Ceiling - interior					+	
C18	Turn signal lamps - front					C21	Seating					†	
C18	Turn signal lamps - side (post 1987)					C14	Floor					1	
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22 Tools - storage							
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door					<b>↓</b>	
C4	Generator or alternator					C18	Red amber signals -					<u> </u>	
C11	Service door					C18	Turn signal lamps - re	ear				<b></b>	
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					-	
	Interior mirror					C19	Strobe light - rear ***			1		┼──	
C6	Speedometer					C17	Identification - rear					+	
C2	Brakes					C4	Exhaust system (no l	eaks)				+	
C21	Driver seat belt					C5	Fuel tank	<i>-</i>				†	
C7	Steering gear	1				C7	Tires (2/32" rear - 4/3	32" front min	ı.)				1
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch					1	
C11	Defroster						Required by forest r	regulation:					
C6	Heaters						Shovel (securely fast	,					
	Wheelchair forward facing (post 1993)						Axe (securely fastene					<u></u>	
	umber reference, Standards for School Buses in l										driver.		
Does I	not apply. ***New buses ordered after 08/15/02.*	Dase(	ı on ongin	iai uapa	iony listed				ae uie DUS.	•			
On fir	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspec	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No	Date				Badge	a No			Date			
		Date_				_	. 110.			Date _			
Signat	ture of District Official					Date							
						1							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Centerville Public Schls** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **4UZZAXAK63CL78185** 2004 2070 Bus Type: (see ? for definition) Chassis Make Body Make Пв ПА ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correc	ted.	0 . 0	,							0100 2)		
	actions to OPI from School District s bus has been sold, retired, or is no longe		ice. Plea	ase d	elete it fr	om OPI	's records.						
	ease make corrections noted below. Don't							ection.					
OPI (	County # and County Name					District Name							
	07 Cascade					Centerville Public Schls							
Vehic	le I.D. # (VIN) - Entire Number		Mod	lel Ye	ear	Licen		iter ville i	Rated C		, ****		
	4ZAAXDDC55CN74335			200	15		2218				60		
Chas	sis Make			_	Body Mak	ie	2210	Bus Type	e: (see ? fo	or defini			
	Facialistica				,			□ A	B	✓ C	□ D		
Freightliner  Wheel Chair Lift Equipped? Wheel Chair Lift Equipped?						omas							
✓ Y			orward				o Fooing N	ot Applia	abla				
	of Fuel:						e Facing	ot Applica		rootor'o	nomo	io:	
		IS DU	15.	ווואוכו	ci Owned		ontractor Owned in co	onitactor ov	viiea, com	liacioi s	Hallie	15.	
□G	as 🗹 Diesel 🗌 Other												
						CTION							
	This	TO inspecti				THE HI	GHWAY PATROL ster	otor					
	THIS	inspecti	Appro		<b>V</b> 15	i semes	L Znd semes	stei			App	roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes		NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front				-	C21	Seating						-
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front  Marker lamps - front				+	C9 C22	Aisle Tools - storage					1	<del> </del>
C18	Windshield					C24	Windows						
C24	Windshield wipers				+	C13	Warning device					1	<del> </del>
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery				1	C12	Emergency door					1	†
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer				-		Identification - rear						
C2	Brakes				1	C4	Exhaust system (no l	eaks)					1
C21	Driver seat belt Steering gear				+	C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front mir	2.)			1	1
C13	Fire extinguisher (5 lbs)				+	C/	Cleanliness	2 11011111111	1.)				1
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.*										driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	9 No.	Date				Badge	e No			Date			
Signa	ture of District Official					Date							
											TR-1	3 Revise	ed 11/04



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name **District Name Belt Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1111 2002 1111 Chassis Make Bus Type: (see ? for definition) Body Make ✓ A  $\square$  B  $\Box$  D Other Other Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ☐ District Owned ✓ Contractor Owned If contractor owned, contractor's name is: Type of Fuel: ✓ Gas Diesel Other Gary Crowder **INSPECTION** TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page Items listed in the Standards Items listed in the Standards Page Corr Yes No NΑ No NA No.\* for School Buses in Montana for School Buses in Montana

C17	Identification - front			C34	Belt cutter **** attached			
C18	Head lamps			C18	Interior lamps			
C10	Color			C18	Ceiling - interior			
C18	Turn signal lamps - front			C21	Seating			
C18	Turn signal lamps - side (post 1987)			C14	Floor			
C18	Red amber signals - front			C9	Aisle			
C18	Marker lamps - front			C22	Tools - storage			
C18	Windshield			C24	Windows			
C24	Windshield wipers			C13	Warning device			
C20	Exterior mirrors			C13	Buzzer emergency door			
C3	Battery			C12	Emergency door			
C4	Generator or alternator			C18	Red amber signals - rear			
C11	Service door			C18	Turn signal lamps - rear			
C6	Head lamp indicator			C18	Stop lamps			
C6	Horn			C18	Marker lamps - rear			
C20	Interior mirror			C19	Strobe light - rear ***			
C6	Speedometer			C17	Identification - rear			
C2	Brakes			C4	Exhaust system (no leaks)			
C21	Driver seat belt			C5	Fuel tank			
C7	Steering gear			C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)				Cleanliness			
C13	First aid kit			C22	Stop arm			
C13	Body fluids kit			C5	No trailer hitch			
C11	Defroster				Required by forest regulation:			
C6	Heaters				Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)				Axe (securely fastened)			
*Page n	umber reference. Standards for School Buses in I	Montana (2002 Fo	dition) ****Bus dri	ivers are	required to wear lap/shoulder belts - cutter atta	ched nearby	driver	

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:					
Approved		Approved					
Not Approved		Not Approved					
Inspecting Patrol Officer:		Inspecting Patrol Officer:					
Badge No.	Date	Badge No.	Date				
Signature of District Official		Date					



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

riigiiw	ay Fatiol as soon as all defects are correct	.cu.											
Instru	ictions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	lelete it fr	om OPI'	's records.									
Ple	ase make corrections noted below. Don't	black ou	ut the erro	or, O	PI may ne	eed to read it to make the correction.							
OPI C	County # and County Name					District Name							
0	reality in all a country training					District Ivalite							
	07 Cascade						В	elt Public Scho	ools				
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Y	ear	Licen	se#	Rated	Capacity	/ ****			
	1FDPJ75A2NVA10752			199			912			60			
Chassis Make Body Ma					Body Mal	ке		Bus Type: (see ?	for defin	ition)			
	Ford					The	omas	$\square$ A $\square$ B	✓ C	$\Box$ D			
Whee	el Chair Lift Equipped?	Whe	el Chair	l ift F	quipped?		Jilias						
<b>✓</b> Ye	es 🗆 No	<b>✓</b> F	orward	l Fa	cing	Aisl	e Facing 🔲 N	ot Applicable					
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	I C	ontractor Owned If co	ntractor owned, co	ntractor's	name	is:		
	as ☑ Diesel ☐ Other												
□G	as 💌 Diesei 🗆 Other												
					INSPE	CTION							
		TC	BE FIL	LED	OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd semes	ster					
		·	Appro							App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in t	the Standards	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Buse	es in Montana			**		
C17	Identification - front					C34	Belt cutter **** attache	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	C24 Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no le	eaks)					
C21	Driver seat belt				_	C5	Fuel tank	Oll for all as'		1	1	1	
C7	Steering gear	-				C7	Tires (2/32" rear - 4/3	2" front min.)		1	1		
C13	Fire extinguisher (5 lbs)					000	Cleanliness			1	1	1	
C13	First aid kit					C22	Stop arm			1	1	1	
C13	Body fluids kit	<u> </u>			-	C5	No trailer hitch			<u> </u>	<u> </u>		
C11	Defroster					1	Required by forest r	•		+	+	1	
C6 C20	Whoolchair forward facing (post 1993)				-	-	Shovel (securely fasters		-	1	1	1	
	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in I	Montana	(2002 E4:+	ion)	****Buc 4	vers are a	Axe (securely fastene		ad noorh	driver	1		
**Does r	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**	vioritaria ( ****Based	(2002 Edit I on oriain:	al cap	ous arr acity listed	on the m	anufacturers certification to	ag found inside the bu	s.	unver.			
		_ 4000	Jg	၁۵۳	,								
	rst inspection, this bus is:						einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Insped	cting Patrol Officer:					Insped	cting Patrol Officer:						
Rador	• No	Date				Rados	No.		Date				
		ם מוכ					e No		Date				
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correc	ted.											
	actions to OPI from School District s bus has been sold, retired, or is no longe	="	/ice. Ple	ease d	elete it fr	om OPI	's records.						
	ase make corrections noted below. Don't	black ou	ut the er	ror, OF	Pl may ne	·							
OPI C	County # and County Name					District Name							
	07 Cascade					Belt Public Schools							
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen	se#		Rated C	Capacity	*****		
1FDPJ75C5PVA19367 1993						1581				60			
					Body Mak	ке		Bus Type	: (see ? fo	or defini			
						Th	amaa	□ A [	⊒в <b></b>	<b>✓</b> C	$\Box$ D		
Whee	Ford el Chair Lift Equipped?	Whe	el Chair	· Lift E	quipped?		omas						
							o Fooing	at Applia	مام				
☐ Ye			orwar					ot Applica					
• •	of Fuel:	IS B	us: 🗸	DISTRIC	ct Owned	ı	ontractor Owned If co	ontractor ow	nea, cont	tractors	name	IS:	
□G	as ☑ Diesel ☐ Other												
					INSPE	CTION							
					OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ster 2nd seme	ster					
D	Harris Patadia tha Otandanda	17	<del></del>	oved	10	D	I Borne Parente.	the Oterates	.1-	1./	<del></del>	roved	10
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach						
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front Windshield					C22 C24	Tools - storage Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors	1				C13	Buzzer emergency de	oor					+
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20 C6	Interior mirror					C19 C17	Strobe light - rear *** Identification - rear					-	
C2	Speedometer Brakes					C17	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank	cans					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min	ı.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r						
C6 C20	Heaters Wheelchair forward facing (post 1993)	1				1	Shovel (securely fast Axe (securely fastene						+
	umber reference, Standards for School Buses in	Montana	(2002 Edi	tion). *	***Bus driv	vers are i	,	,	ter attache	d nearby	driver.	1	1
	not apply. ***New buses ordered after 08/15/02.*												
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	e No.	Date				Badge	e No.			Date			
	ture of District Official					Date	<del></del>						
Jigila	J. Block of Gilloldi					Jule							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Belt Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBL6P1G6LV109686 1990 735 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D Chevrolet **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Belt Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1707 1GDL7T1J0TJ501675 1995 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **GMC Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Thigh may a wife as both as an action and both sound.														
Instructions to OPI from School District:														
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ase	delete it fr	om OPI	s records.							
☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, C	DPI may ne									
OPI C	County # and County Name					District Name								
	07 Cascade							<u>elt Public Scho</u>						
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Y	⁄ear	Licen	se #	Rated	Capacity	, ****				
	1HVBBABP4SH630069			10	94		1756			60				
Chas	sis Make			Ť	Body Mak	e	1700	Bus Type: (see ?	for defin					
0					200,a.									
	International						omas	□ A □ B	✓ C	∐ D				
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift	Equipped?	<u></u>								
☐ Y	es 🗹 No	│□F	orwar	d Fa	acina [	☐ AisI	e Facing 💆 N	ot Applicable						
	of Fuel:						ontractor Owned If co		ntractor's	name	is.			
		10 5	uo. 🔻	Diot	not Owned		ontractor owned in co	initiation ownica, co	intraotor c	riairio				
$\Box$ G	as ☑ Diesel ☐ Other													
					INSPE	CTION								
		TC	BE FIL	LEC			GHWAY PATROL							
	This	inspect	ion is foi	r:	<b>✓</b> 1s	t semes	ter 2nd semes	ster						
		·	Appr	oved						App	roved			
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in		Yes	No	NA	Corr		
No.*	for School Buses in Montana			**		No.*	for School Bus				**			
C17	Identification - front					C34	Belt cutter **** attache	ed				_		
C18	Head lamps					C18	·							
C10	Color					C18	Ceiling - interior					_		
C18	Turn signal lamps - front					C21	ÿ				-	4		
C18	Turn signal lamps - side (post 1987)					C14 C9						_		
C18	Red amber signals - front  Marker lamps - front					C22					1	-		
C18	Windshield					C24	ĕ					+		
C24	Windshield wipers					C13 Warning device					1			
C20	Exterior mirrors					C13 Buzzer emergency door					1			
C3	Battery					C12 Emergency door			1		1	1		
C4	Generator or alternator					C18	Red amber signals -	rear				1		
C11	Service door					C18	Turn signal lamps - re	ar						
C6	Head lamp indicator					C18	Stop lamps							
C6	Horn					C18	Marker lamps - rear							
C20	Interior mirror					C19	Strobe light - rear ***					-		
C6	Speedometer					C17	Identification - rear							
C2	Brakes					C4	Exhaust system (no le	eaks)				-		
C21	Driver seat belt					C5 C7	Fuel tank Tires (2/32" rear - 4/3	O" front min \				+		
C13	Steering gear Fire extinguisher (5 lbs)					C/	Cleanliness	2 HOHL Min.)	+		<u> </u>	+		
C13	First aid kit					C22	Stop arm					+		
C13	Body fluids kit					C5	No trailer hitch					1		
C11	Defroster					-	Required by forest r	egulation:				1		
C6	Heaters						Shovel (securely faste	•				1		
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene					1		
	umber reference, Standards for School Buses in Not apply. ***New buses ordered after 08/15/02.**									driver.				
	rst inspection, this bus is:						inspection, this bus							
	Approved						Approved	13.						
H	Not Approved						Not Approved							
	cting Patrol Officer:						cting Patrol Officer:							
ape						ape	g : all of Officer.							
Badge	No	Date				Badge	No		_ Date _					
Signa	ture of District Official					Date								



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Belt Public Schools** 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 4UZ3CFBAOXCB73618 1999 1885 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highwa	ay Patrol as soon as all defects are correc	ted.												
Instructions to OPI from School District:														
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.														
Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.														
OPI County # and County Name						District Name								
or robuitly if and obuitly Name						Distri	ot Name							
07 Cascade							В	elt Public	Schoo	ols				
Vehicle I.D. # (VIN) - Entire Number Model Year						Licen			Rated C		****			
	4UZAAXAK82CJ35055			200			1129				60			
Chass	sis Make				Body Mal	ке		Bus Type	: (see ? fo	or defini	tion)			
	Freightliner					0	ther	$\square$ A	□в [	<b>✓</b> C	$\Box$ D			
Whee	Chair Lift Equipped?	Whe	el Chair	l ift F	quipped?		uici							
☐ Ye	es 🗹 No	L F	orward	d Fa	cing	_ Aisl	e Facing 💆 N	ot Applica	able					
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	I 🗌 C	ontractor Owned If co	ntractor ow	ned, cont	tractor's	name i	s:		
□G	as ☑ Diesel ☐ Other													
	as Diesei - Othei													
					INSPE	CTION								
					OUT BY	THE HI	GHWAY PATROL							
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd semes	ster						
			Appro	oved							Appı	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in			Yes	No	NA **	Corr	
No.*	for School Buses in Montana					No.*	for School Bus		ina					
C17	Identification - front					C34	Belt cutter **** attach	ed						
C18	Head lamps					C18	Interior lamps							
C10	Color					C18	Ceiling - interior							
C18	Turn signal lamps - front					C21 Seating								
C18	Turn signal lamps - side (post 1987)  Red amber signals - front					C14 Floor C9 Aisle					<u> </u>			
C18	Marker lamps - front				+		C22 Tools - storage				<del>                                     </del>	<del> </del>		
C18	Windshield					C24 Windows						<del>                                     </del>		
C24	Windshield wipers				+	C13 Warning device								
C20	Exterior mirrors					C13 Buzzer emergency door								
C3	Battery					C12	Emergency door	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
C4	Generator or alternator					C18	Red amber signals -	rear						
C11	Service door					C18	Turn signal lamps - re							
C6	Head lamp indicator					C18 Stop lamps								
C6	Horn					C18	Marker lamps - rear							
C20	Interior mirror					C19	Strobe light - rear ***							
C6	Speedometer					C17	Identification - rear							
C2	Brakes					C4	Exhaust system (no le	eaks)						
C21	Driver seat belt					C5	Fuel tank				<u> </u>	<u> </u>		
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min	1.)		ļ	<u> </u>		
C13	Fire extinguisher (5 lbs)	1			-	000	Cleanliness					<b></b>		
C13	First aid kit	1	1		4	C22	Stop arm			<u> </u>	<del>                                     </del>	<del>                                     </del>	ļ	
C13	Body fluids kit					C5	No trailer hitch				<b></b>	<u> </u>		
C11	Defroster						Required by forest r					<u> </u>		
C6 C20	Heaters Wheelchair forward facing (post 1993)	1	1		+	-	Shovel (securely fastene Axe (securely fastene				<del>                                     </del>	<del>                                     </del>	1	
	umber reference, Standards for School Buses in	Montana	(2002 Edit	ion) '	***Rue driv	vers are i	, ,	,	ter attache	d nearby	driver		<u> </u>	
	not apply. ***New buses ordered after 08/15/02.**										alivol.			
0	est increation this busis		-			0	inopostica di la la	io.						
	est inspection, this bus is:						einspection, this bus	15.						
	Approved Not Approved						Approved Not Approved							
	• •						• •							
inspec	eting Patrol Officer:					inspe	cting Patrol Officer:							
Badge	No	Date				Badge	e No			Date				
	ture of District Official	-	-			Date		-		_				
- 3														



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.

Instructions to OPI from School District:										
☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.										
Please make corrections noted below. Don't bla	ack out the error, 0	OPI may need to re	ead it to make the cor	rection.						
OPI County # and County Name		Distri	ct Name							
07 Cascade		В	Belt Public	Schools						
Vehicle I.D. # (VIN) - Entire Number	Vehicle I.D. # (VIN) - Entire Number Model Yea				Rated Capacity *****					
4UZAAXDD34CM52452	20	003	2150		65					
Chassis Make	Body Make Bu				Bus Type: (see ? for definition)					
Freightliner			omas	□ A □	B C D					
Wheel Chair Lift Equipped?	Wheel Chair Lift	Equipped?								
☐ Yes ☑ No	☐ Forward Fa	acing $\square$ Aisl	e Facing 🔽 N	lot Applical	ble					
Type of Fuel:	Is Bus: 🗸 Dist	trict Owned 🔲 Co	ontractor Owned If c	ontractor own	ned, contractor's name is:	:				
☐ Gas ☑ Diesel ☐ Other										
INSPECTION										
	_	D OUT BY THE HI	_							
This in	nspection is for:	✓ 1st semes	ter 2nd seme	ester						
	Approved				Appro					
Page Items listed in the Standards	Yes No NA	Corr Page	Items listed in	the Standard	ls Yes No	NA Corr				

No.\* No.\* for School Buses in Montana for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear C11 C18 Turn signal lamps - rear Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt C5 Fuel tank Steering gear Tires (2/32" rear - 4/32" front min.) Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On reinspection, this bus is:
Approved
Not Approved
Inspecting Patrol Officer:
e Date
Date
Not Approved Inspecting Patrol Officer:  Badge No Date



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highway Patrol as soon as all defects are corrected.													
Instructions to OPI from School District:													
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
	ase make corrections noted below. Don't							ection.					
OPI County # and County Name						District Name							
0110	bounty # and obunty Name					Distri	ot Name						
07 Cascade							V	aughn Ele	ementa	ary			
Vehicle I.D. # (VIN) - Entire Number Model Year					Licen	se#		Rated C	apacity	*****			
	4555 15500511404400			400			4055						
	1FDPJ75C6PUA31186			199			1055	Dua Tura	/ 0 f-	l <b>f</b> ::	78		
Chas	sis Make				Body Mal	ке		Bus Type:	(see ? ic	or delini	ition)		
	Ford					The	omas	$\Box$ A $\Box$	]в 🤄	✓ C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	r Lift E	quipped?								
							- Fi	-4 A!:	L.I.				
☐ Ye			orwar					ot Applical					
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	ı	ontractor Owned If co	ontractor own	ned, cont	ractor's	name	is:	
□G	as ☑ Diesel ☐ Other												
					_	CTION	01 1144 AV DATDOI						
	<del>-</del>						GHWAY PATROL						
	Ihis	inspect	ion is fo		<b>✓</b> 1s	t semes	ster 2nd seme	ster					
Page	Items listed in the Standards	Vac	Appr No	roved	Co	Done	المعمم المدعا ا	tha Ctar-l-	lo.	Vac		noved NA	Cor
No.*	for School Buses in Montana	Yes	INO	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	**	Corr
C17	Identification - front					C34	Belt cutter **** attach		<u></u>			+	
C18	Head lamps					C18	Interior lamps				1	+	
C10	Color					C18	Ceiling - interior					+	
C18	Turn signal lamps - front					C21 Seating							
C18	Turn signal lamps - side (post 1987)					C14 Floor							
C18	Red amber signals - front					C9	C9 Aisle						
C18	Marker lamps - front					C22							
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13 Buzzer emergency door							
C3	Battery					C12 Emergency door				<b>↓</b>			
C4	Generator or alternator					C18	Red amber signals -					<b>↓</b>	
C11	Service door					C18	Turn signal lamps - re	ear			<u> </u>	+	
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					+	
C20	Interior mirror					C19	Strobe light - rear ***					+-	
C6	Speedometer					C17	Identification - rear				1	+	
C2	Brakes					C4	Exhaust system (no l	eaks)				+	
C21	Driver seat belt					C5	Fuel tank					1	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.	)			1	
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	_				<b>↓</b>	
C6	Heaters						Shovel (securely fast					ـــــــ	
C20	Wheelchair forward facing (post 1993)		(2222 = 1	\ .			Axe (securely fastene			<u>.                                    </u>	<u> </u>		
	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.*										driver.		
		Dasce	. on ongi	.a. oape	iony notou				Dus.				
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No.			Date			
	ture of District Official				-	Date	-						
Oigila	and of District Official					Date							



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

- Ingriting - Inter- are the controlled.														
Instructions to OPI from School District:														
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.														
Please make corrections noted below. Don't black out the error, OPI may no														
OPI County # and County Name					District Name									
or recently wante county manne														
07 Cascade					Vaughn Elementary									
Vehicle I.D. # (VIN) - Entire Number Model Year					License # Rated Capacity *****									
4UZ6CFAA9XCA95306				1999			269		48					
Chassis Make				Body Make					pe: (see ? for definition)					
Chassis Make			20a)a.											
Freightliner				Thomas				□ A □ B	□B ☑C □D					
Wheel Chair Lift Equipped? Wheel			el Chair	Lift I	Equipped?	1								
☐ Yes ☑ No ☐ Fo			orwar	d Fa	acina [	☐ AisI	e Facing 🗹 N	ot Applicable						
			Forward Facing ☐ Aisle Facing ☑ Not Applicable us: ☑ District Owned ☐ Contractor Owned If contractor owned, contractor's r							name	is.			
		10 5	13 Das. P District Owned   Contractor Owned   Contractor Owned, Contractor 5 Hallie 15.											
$\Box$ G	as ☑ Diesel ☐ Other													
					INSPE	CTION								
		TC	BE FIL	LED			GHWAY PATROL							
	This	inspect	ion is fo	r:	<b>✓</b> 1s	t semes	ster 2nd semes	ster						
		·	Appr	oved						Арр	roved			
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in		Yes	No	NA	Corr		
No.*	for School Buses in Montana			**		No.*	for School Bus				**			
C17	Identification - front					C34		Belt cutter **** attached						
C18	Head lamps					C18	Interior lamps		ļ					
C10	Color					C18		Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating		1	1				
C18	Turn signal lamps - side (post 1987)					C14 C9	Floor Aisle				-			
C18	Red amber signals - front  Marker lamps - front					C22	Tools - storage		1	1	1			
C18	Windshield					C24	Windows							
C24	Windshield wipers					C13	Warning device							
C20	Exterior mirrors					C13	Buzzer emergency door							
C3	Battery					C12	Emergency door			1	1	1		
C4	Generator or alternator					C18	Red amber signals - rear							
C11	Service door					C18	Turn signal lamps - rear							
C6	Head lamp indicator					C18	Stop lamps							
C6	Horn					C18	Marker lamps - rear							
C20	Interior mirror					C19	Strobe light - rear ***							
C6	Speedometer					C17	Identification - rear							
C2	Brakes					C4	Exhaust system (no leaks)			1	1			
C21	Driver seat belt Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front min \		1	1	1		
C13	Fire extinguisher (5 lbs)					C/	Cleanliness	<u> </u>				1		
C13	First aid kit					C22	Stop arm		+	1	1	+		
C13	Body fluids kit					C5	No trailer hitch							
C11	Defroster						Required by forest r	egulation:			1			
C6	Heaters						Shovel (securely faste	-		t	t			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)								
	umber reference, Standards for School Buses in Not apply. ***New buses ordered after 08/15/02.**									driver.				
On fi	rst inspection, this hus is:				<u>'</u>	On re	inspection this hus	is:						
On first inspection, this bus is:						On reinspection, this bus is:  Approved								
Not Approved						☐ Not Approved								
Inspecting Patrol Officer:			Inspecting Patrol Officer:											
Badge No Date				Badge No Date										
Signature of District Official					Date									



Fire extinguisher (5 lbs)

Wheelchair forward facing (post 1993)

First aid kit

Defroster

Heaters

Body fluids kit

C13

C13

C11

C6

C20

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena MT 59620-2501

#### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 07 Cascade Vaughn Elementary Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 4UZAAXCS43CL0082 2003 660 70 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

	On reinspection, this bus is:					
	Approved					
	Not Approved					
Inspecting Patrol Officer:		Inspecting Patrol Officer:				
Date	Badge No.	Date				
	Date					
		Approved Not Approved Inspecting Patrol Officer: Badge No.				

C22

C5

Cleanliness

No trailer hitch

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)

Stop arm



C13

C13

C11

C6

C20

First aid kit

Defroster

Heaters

Body fluids kit

Wheelchair forward facing (post 1993)

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 07 Cascade **Ulm Elementary** Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBBCFP6LH693715 1580 1990 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Ward International Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

	On reinspection, this bus is:					
	Approved					
	Not Approved					
Inspecting Patrol Officer:		Inspecting Patrol Officer:				
Date	Badge No.	Date				
	Date					
		Approved Not Approved Inspecting Patrol Officer: Badge No.				

C22

C5

Stop arm

No trailer hitch

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highw	ay Patrol as soon as all defects are correc	ted.											
	actions to OPI from School District s bus has been sold, retired, or is no longe	-	rice. Ple	ase d	elete it fr	om OPI	's records.						
	ase make corrections noted below. Don't County # and County Name	black ou	it the err	or, OF	PI may ne		ead it to make the corr	ection.					
OFIC	Journy # and County Name					DISTI	ct Name						
	07 Cascade							Ulm Ele					
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Ye	ear	Licen	se #		Rated C	Capacity	, ****		
	1HVLPHYM1PHA60469			198	35		1257				48		
Chas	sis Make				Body Mal	е		Bus Type	: (see ? f	or defini			
						DI.	الماد الماد	□A	□ B [	<b>✓</b> C	$\Box$ D		
Whee	International  Chair Lift Equipped?	Whe	el Chair	Lift F	quipped?		ebird						
		l											
☐ Ye			orward					ot Applica					
Type	of Fuel:	Is B	us: 🗸	Distri	ct Owned	ı	ontractor Owned If co	ontractor ov	vned, con	tractor's	name	S:	
$\Box$ G	as 🗹 Diesel 🗌 Other												
					INSPE	CTION							
		TC	BE FIL	LED	_	-	GHWAY PATROL						
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd seme	ster					
			Appro								Арр	roved	
Page	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
No.*	Identification - front					C34	Belt cutter **** attach		ana			$\vdash$	+
C18	Head lamps					C18	Interior lamps	ieu				+	+
C10	Color					C18	Ceiling - interior						†
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9					Ь		
C18	Marker lamps - front						C22 Tools - storage			—			
C18 C24	Windshield Windshield wipers					C24 Windows C13 Warning device			├─	_			
C20	Exterior mirrors					C13	Buzzer emergency de	oor				+	+
C3	Battery					C12	Emergency door	001				+	+
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps					—	
C6 C20	Horn Interior mirror					C18 C19	Marker lamps - rear Strobe light - rear ***					┼	+
C20	Speedometer					C17	Identification - rear					+-	+
C2	Brakes					C4	Exhaust system (no l	eaks)				+	+
C21	Driver seat belt					C5	Fuel tank	,				<b>†</b>	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front mir	า.)				
C13	Fire extinguisher (5 lbs)					000	Cleanliness					—	—
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch					┼	+
C13	Defroster Defroster					Co	Required by forest r	regulation:				$\vdash$	+
C6	Heaters						Shovel (securely fast					+	+
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene					<b>†</b>	
*Page n	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.*										driver.		
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved	**					
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No.			Date			
	ture of District Official					Date							
Jigila	and a plantat official					Jule							



Date

Signature of District Official

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 2004 Temp Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D Other Other Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Treasure State Transit INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAAGCSH2KF030695 1989 1291 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAAGCSH4KF030696 1989 1292 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No. Signature of District Official Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAAGCSH4KF030701 1989 1303 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

	actions to OPI from School District:		ico Plos		doloto it fr	om OBI	's records							
	s bus has been sold, retired, or is no longe ase make corrections noted below. Don't							ection						
	County # and County Name	black oc	it the chic	,, c	or rinay in									
0	07 Cascade					District Name Sun River Valley Pub Schls								
Vehic	le I.D. # (VIN) - Entire Number		Mod	el Y	'ear	Licen		tivei vai		Capacity				
	, ,			20	102		2400							
Chas	1BAAKCPH63F210173 sis Make			7	003 Body Mal	Δ	2108	Bus Type	: (see ? f	for defin	72			
Cilas					Dody Mai	(C		_	`	_	,			
\A/I	Bluebird	I 14/1	-1 011-1	.,.	<b>-</b> 10		ebird	□ A	В		_ C			
	el Chair Lift Equipped?				Equipped?	_	_							
□ Y			orward	Fa	acing	Aisl	e Facing 🔽 N	ot Applic	able					
Туре	of Fuel:	Is Bu	ıs: 🗸 [	Dist	rict Owned	I C	ontractor Owned If co	ontractor ov	vned, con	tractor's	name	is:		
$\square$ G	as ☑ Diesel ☐ Other													
		т.	DE EU 1		_	CTION	OLUMAY BATBOL							
	This		on is for:		_	t semes	GHWAY PATROL ster	ster						
			Appro								Арр	roved		
Page No.*	Items listed in the Standards for School Buses in Montana	Yes		NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr	
C17	Identification - front					C34	Belt cutter **** attach	ed						
C18	Head lamps					C18	Interior lamps							
C10	Color					C18	Ceiling - interior							
C18	Turn signal lamps - front					C21	Seating							
C18	Turn signal lamps - side (post 1987)						C14 Floor							
C18	Red amber signals - front  Marker lamps - front					C22	C9 Aisle					<u> </u>		
C18	Windshield	1				C22 Tools - storage C24 Windows		+		1				
C24	Windshield wipers					C13								
C20	Exterior mirrors					C13	Buzzer emergency do	oor						
C3	Battery	1				C12	Emergency door			1				
C4	Generator or alternator					C18	Red amber signals -	rear						
C11	Service door					C18	Turn signal lamps - re	ear						
C6	Head lamp indicator					C18	Stop lamps							
C6	Horn					C18	Marker lamps - rear							
C20	Interior mirror					C19	Strobe light - rear ***							
C6	Speedometer					C17	Identification - rear	1>		-				
C2	Brakes					C4	Exhaust system (no l	eaks)				<u> </u>		
C21	Driver seat belt Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front mi	2.)					
C13	Fire extinguisher (5 lbs)	1				0,	Cleanliness	2 11011111111	1.)	+	<u> </u>			
C13	First aid kit					C22	Stop arm							
C13	Body fluids kit					C5	No trailer hitch							
C11	Defroster						Required by forest r	egulation:						
C6	Heaters						Shovel (securely fast	ened)						
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,						
- 3	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**			- /						,	driver.			
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:						
	Approved						Approved							
	Not Approved						Not Approved							
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:							
Badge	• No	Date			<u> </u>	Badge	e No.			Date				
Signa	ture of District Official					Date								



### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **1BAANCPH6YF093497** 2000 1936 78 Bus Type: (see ? for definition) Chassis Make Body Make ПА □в ✓ C  $\Box$  D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C18 C6 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch Defroster C11 Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
<b>-</b>		<b>-</b>	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highway Patrol as soon as all defects are corrected.													
Instru	ictions to OPI from School District												
	s bus has been sold, retired, or is no longe		ice. Ple	ase d	elete it fr	om OPI	's records.						
	ase make corrections noted below. Don't							ection.					
	County # and County Name						ct Name						
0110	odity # and oddity Name					Distri	ot Name						
	07 Cascade						Sun F	River Vall	ey Pub	Schl	S		
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen	se#		Rated C	Capacity	*****		
	4001			400			050						
	1GBL7T1C2WJ111322			199	_		958	D T	/ O (	l - C - '	72		
Chass	sis Make				Body Mak	се		Bus Type	: (see ? 10	or aetini	ition)		
	Chevrolet					Blu	ebird	$\square$ A	□ B :	<b>✓</b> C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?			<u> </u>					
					· · · ·	¬ ∧:-ı	- Fi	-4 AI'					
☐ Ye			orwar					ot Applica					
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	ı	ontractor Owned If co	ontractor ow	ned, cont	tractor's	name	is:	
□ G	as ☑ Diesel ☐ Other												
					_	CTION	01 114 4 1						
	<del>-</del>						GHWAY PATROL						
	This	inspect	ion is fo		<b>✓</b> 1s	t semes	ster 2nd seme	ster					
Dow-	Itomo liotad in the Ctandard	Vac	Appr		Corr	Done	Items listed in	tha Ctar-I	do	Vac		noved NA	Corr
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	for School Bus			Yes	No	**	Corr
C17	Identification - front					C34	Belt cutter **** attach					+	
C18	Head lamps	1				C18	Interior lamps	Cu				+	+
C10	Color					C18	Ceiling - interior					+	
C18	Turn signal lamps - front					C21	Seating					+	
C18	Turn signal lamps - side (post 1987)					C14	Floor					1	
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22 Tools - storage							
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door					<b>↓</b>	
C4	Generator or alternator					C18	Red amber signals -					<b>↓</b>	
C11	Service door					C18	Turn signal lamps - re	ear				<b>↓</b>	
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					+	
	Interior mirror					C19	Strobe light - rear ***					+	+
C6	Speedometer					C17	Identification - rear					+	
C2	Brakes					C4	Exhaust system (no l	eaks)				+	
C21	Driver seat belt				1	C5	Fuel tank					<b>†</b>	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min	1.)				
C13	Fire extinguisher (5 lbs)						Cleanliness					1	
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	_					
C6	Heaters	1	ļ		1		Shovel (securely fast	,		<u> </u>	<u> </u>	—	1
	Wheelchair forward facing (post 1993)		(2222 5 11				Axe (securely fastene			<u>.                                    </u>	<u> </u>		
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.*										driver.		
		Dase	. Jii Jiigiii	ai oape	iony notou					•			
	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspec	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	e No.			Date			
	ture of District Official					Date							-
Signal	uie oi District Official					Date							
						1							



Date

Signature of District Official

## **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected

1 ligitw	ay Fallol as soon as all delects are correc	icu.											
	octions to OPI from School District s bus has been sold, retired, or is no longe		rice. Ple	ase d	elete it fr	om OPI	's records.						
☐ Ple	Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.												
OPI County # and County Name						Distri	ct Name						
	07 Cascade						Sun F	River Valle	v Pub	Schl	S		
Vehic	le I.D. # (VIN) - Entire Number		Mod	del Ye	ar	Licen			Rated C				
	1GBL7T1J0TJ100782			199	5		1335				66		
Chass	sis Make			E	Body Mak	е		Bus Type:	(see ? fo	or defini	tion)		
	Chevrolet					Blu	ıebird	□ A □	В	✓ C	$\Box$ D		
Whee	Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?	)							
□ Ye	es 🗹 No	☐ F	orward	d Fac	ing [	☐ Aisl	e Facing <b>☑</b> N	ot Applicat	ole				
Туре	of Fuel:	Is B	us: 🗸	Distric	ct Owned	_ C	ontractor Owned If co	ontractor own	ed, cont	tractor's	name	is:	
□G	as 🗹 Diesel 🗌 Other												
					INSPE	CTION							
		т	BE FIL	LED (			GHWAY PATROL						
	This	inspect	ion is for	:	<b>✓</b> 1s	t semes	ster 2nd seme	ster					
			Appro								App	roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach	ed					1
C18	Head lamps					C18	Interior lamps						1
C10	Color					C18	Ceiling - interior						1
C18	Turn signal lamps - front					C21	Seating						1
C18	Turn signal lamps - side (post 1987)					C14 Floor			1				
C18	Red amber signals - front					C9 Aisle			Ī				
C18	Marker lamps - front					C22 Tools - storage							
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -					Ь	
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						_
C6	Horn					C18	Marker lamps - rear						_
C20	Interior mirror	<u> </u>			-	C19	Strobe light - rear ***					₩	-
C6	Speedometer					C17	Identification - rear	!				┼	-
C2	Brakes Driver seat belt					C4	Exhaust system (no l	eaks)				<del> </del>	-
C21	Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front min )				+	+
C13	Fire extinguisher (5 lbs)					C/	Cleanliness	2 110111 111111.)				+	+
C13	First aid kit					C22	Stop arm					+	+
C13	Body fluids kit	<del> </del>			1	C5	No trailer hitch					+	+
C11	Defroster	1			1	00	Required by forest r	egulation:				+	1
C6	Heaters						Shovel (securely fast	_				+	+
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,			1	t	<b>†</b>
*Page ni	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.**	Montana	2002 Edit	ion). *	***Bus driv	vers are i	required to wear lap/shoul	der belts - cutte	r attache	d nearby	driver.		-
	est inspection, this bus is:		. J.: Jiigiii	Jupo	,		einspection, this bus		546.				
	Approved						Approved						
	Not Approved						Not Approved						
	eting Patrol Officer:					Inspecting Patrol Officer:							
inspecting range onto .					mape	g i ali oi Oilloci							

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBL7T1J0TJ108476 1996 993 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D Chevrolet **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highw	ay Patrol as soon as all defects are correc	ted.											
Instru	ctions to OPI from School District												
Thi	s bus has been sold, retired, or is no longe	er in serv	ice. Ple	ease d	elete it fr	om OPI	's records.						
	ase make corrections noted below. Don't							ection.					
	County # and County Name					District Name							
0110	bounty # and obunty Name					Distri	ot Name						
	07 Cascade						Sun F	River Vall	ey Pub	Schl	S		
Vehic	le I.D. # (VIN) - Entire Number		Mo	del Ye	ar	Licen	se#		Rated C	Capacity	****		
	4 O D I = T.4 I O D I 4 O O O 4 O			400			4040						
- 01	1GBL7T1J9RJ108243			199			1643	Dua Tura	. / 0 6		66		
Chas	sis Make				Body Mal	ке		Bus Type	: (see ? 1	or aetini	tion)		
	Bluebird					Blu	ebird	$\Box$ A	□ B [	<b>✓</b> C	$\Box$ D		
Whee	el Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?								
		I ┌ .		J = .	· · · ·	¬ ∧:-ı	- Casina - A N	-4 A1:	.  -   -				
☐ Ye			orwar					ot Applica					
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	ı	ontractor Owned If co	ontractor ow	ned, con	tractor's	name	s:	
□G	as ☑ Diesel ☐ Other												
				. ==	_	CTION	0111111111						
	<del>-</del>						GHWAY PATROL						
	Ihis	inspect	ion is fo		<b>✓</b> 1s	t semes	ster 2nd seme	ster					
Page	Itoma listed in the Ctandards	Vac	Appr No	oved	Com	Done	liama listadii	tha Ctar-Ir	do	Vac		roved NA	Corr
No.*	Items listed in the Standards for School Buses in Montana	Yes	INO	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	**	Corr
C17	Identification - front					C34	Belt cutter **** attach					+	
C18	Head lamps					C18	Interior lamps	<u> </u>		1		+	
C10	Color					C18	Ceiling - interior					†	
C18	Turn signal lamps - front					C21	Seating					1	
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle					1	
C18	Marker lamps - front					C22 Tools - storage							
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery					C12	Emergency door					↓	
C4	Generator or alternator					C18	Red amber signals -					<b>↓</b>	
C11	Service door					C18	Turn signal lamps - re	ear		1		<b>├</b>	
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear					┼──	
C20	Interior mirror					C19	Strobe light - rear ***			1		+	
C6	Speedometer					C17	Identification - rear			1		+	
C2	Brakes					C4	Exhaust system (no l	eaks)				+	
C21	Driver seat belt				1	C5	Fuel tank	/				<u> </u>	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min	1.)			1	
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	_				<b>↓</b>	
C6	Heaters						Shovel (securely fast	,				↓	
C20	Wheelchair forward facing (post 1993)		(2222 5 11				Axe (securely fastene			<u>.                                    </u>			
	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.*										driver.		
		Ваосс	on ongii	iai oape	torty notou					•			
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	No.	Date				Badge	No.			Date			
	ture of District Official				-	Date	-						
Oigila	and of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBBPEP3NH460791 1992 1533 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBBPEP6PH527290 1993 1590 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBBPEP9NH424796 1501 1992 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is:

On first inspection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.
Date
Badge No.
Date
TR-13 Revised 11/04



C6

C20

Heaters

Wheelchair forward facing (post 1993)

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena MT 59620-2501

### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name Sun River Valley Pub Schls 07 Cascade Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 4UZ3CJAA3WC889879 1002 1998 66 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page Items listed in the Standards NΑ No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C18 C6 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch Defroster C11 Required by forest regulation:

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	

Shovel (securely fastened)

Axe (securely fastened)

TR-13 Revised 11/04



C20

C13

C13

C11

C6

C6

Interior mirror

Speedometer

Driver seat belt

Fire extinguisher (5 lbs)

Wheelchair forward facing (post 1993)

Steering gear

Body fluids kit

First aid kit

Defroster

Heaters

Brakes

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena, MT 59620-2501

#### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 07 Cascade Sun River Valley Pub Schls Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 4UZAAXCS34CM32637 2004 1074 64 Bus Type: (see ? for definition) Chassis Make Body Make ПА □в ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL ✓ 1st semester 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No Items listed in the Standards Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior C18 Turn signal lamps - front C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:		On reinspection, this bus is:	
Approved		Approved	
Not Approved		■ Not Approved	
Inspecting Patrol Officer:		Inspecting Patrol Officer:	
Badge No.	Date	Badge No.	Date
Signature of District Official		Date	

C19

C17

C4

C22

C5

Strobe light - rear \*\*\*

Exhaust system (no leaks)

Tires (2/32" rear - 4/32" front min.)

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)

Identification - rear

Fuel tank

Stop arm

Cleanliness

No trailer hitch